

Information:907 Sprinter 15 Passenger Van Trailer Hitch

Topic number	LI31.00-N-069787
Version	1
Function group	31.00 General
Date	05-23-2019
Validity	Sprinter 15 seat passenger van (907.745)
Reason for change	
Reason for block	

Complaint:

Customer would like to have trailer hitch installed

Cause:

Trailer towing restriction of the 15 passenger Vans

Installation of a trailer hitch is not allowed

Remedy:

Due to the vehicles GCWR it is not possible for 15 passenger 907 Sprinter variants to be equipped with a trailer hitch.

Please advise the customer accordingly

DO NOT install or replace any parts.

NOTE: Vehicles may appear to have E40 (trailer hitch prep.wiring) connector, regardless of the presence of the connector a trailer hitch cannot be installed.

Attachments	
File	Description
Trailer hitch pre-wiring.jpg	E40 (trailer hitch prep wiring)

Symptoms
Chassis/suspension / Trailer hitch / Trailer Hitch / General

Validity		
Vehicle	Engine	Transmission
Sprinter 907 - 907.745	*	*

Attachments

XENTRY TIPS

Trailer hitch pre-wiring.
jpg:

