


## Latest Vehicle Concern Fixes



DEF Quality Message	F-Pace, XE, XF, RR Velar equipped with AJ20D
<p><b>Customer Voice:</b></p> <ul style="list-style-type: none"><li>• Incorrect DEF Quality &amp; No Restarts in XXX Miles on the IPC</li></ul> <p><b>Technical Description:</b></p> <ul style="list-style-type: none"><li>• This reoccurring DEF Quality Message is in conjunction with P2BA9, P2BAE, P2BAF stored in the PCM.</li></ul> <p><b>Status:</b></p> <ul style="list-style-type: none"><li>• This software has been delayed until the middle of July with a manual patch expected in the beginning of July. If you have escalated customer cases which are currently awaiting this software, please work with your field representative for customer satisfaction.</li></ul>	 <p>The image shows a close-up of a vehicle's infotainment screen. At the top, it displays the time '15:51' on the left and the temperature '18°C' on the right. Below the time and temperature, it says 'Press [OK] To Clear'. In the center, there is a yellow triangular warning icon with an exclamation mark. At the bottom, the text reads: 'No Engine Restarts In 509 miles Incorrect Diesel Exhaust Fluid Quality Detected'.</p>

