

**** SOLUTION ****

Title	Volvo Chassis - Volvo Parking Cooler System, Technical Information And Diagnostic Guide - Model Year 2018 And Newer
-------	---

Volvo Models

Volvo Model	VN , VNL , VNR , VNX
-------------	----------------------

**** SOLUTION ****

Cause	General Volvo Parking Cooler System information.
-------	--

Solution	For more information regarding the Volvo Parking Cooler System refer to the documents below.
----------	---

[Volvo Parking Cooler System](#)

[Volvo Parking Cooler System Technical Information and Diagnostic Guide](#)

Relay 41, Rly 41

Internal comments (BO)	If you get a call or case on inop parking heater and truck has parking cooler then look at page 11 of the .PDF named Volvo 6-25-2018. There is no relay 41 in trucks that have parking cooler. You can look in EDB to see if trucks have parking cooler. Variant is in function group 873. Below is one example but there are other options.
------------------------	--

873 4BX AUX. CLIMATE UNIT AUXCU-A ADDITIONAL CLIMATE UNIT, AUTOMATIC

Solution visibility	Dealer distribution
---------------------	---------------------

Function(s)/component(s) affected

Function affected	Parking cooler
-------------------	----------------

Function Group

Function Group	878 parking cooler
----------------	--------------------

Customer effect

Main customer effect	temperature
----------------------	-------------

Administration

Author	A241298
--------	---------

Dealer ID	A241298
-----------	---------

Last modified by	RU4469V
------------------	---------

Creation date	22-02-2019 16:02
---------------	------------------

Date of last update	09-08-2019 22:08
---------------------	------------------

Status

Published
