

TEMSA ULAŞIM ARAÇLARI  
SANAYİ VE TİCARET A.Ş.

ADANA FABRİKA  
Sarıhamzalı Mahallesi,  
Turhan Cemal Beriker Bulvarı,  
No :563/A 01110 Seyhan /Adana  
T +90 322 441 02 26  
F +90 322 441 08 74  
info@temsa.com  
www.temsa.com

Mersis No: 0838004674900010  
Yüreğir V.D / 8380046749



September 9th, 2019

## IMPORTANT SAFETY RECALL

**This notice applies to your vehicle(s) [«VIN»]**

>>Customer Name<<  
>>Date<<  
>>Adress<<  
>>Country<<

**SUBJECT:** Hydraulic Hoses May Leak

**Ref: NHTSA 19V557**

Attention Owner:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Temsa Ulaşım Araçları Sanayi ve Ticaret A.Ş. (Temsa) is recalling certain model year 2014-2015-2016-2017-2018-2019 TS45 motorcoaches manufactured between March 2014, to December 2018. The hydraulic hoses of the steering system may leak or burst during operation of vehicle. The hoses are located between the steering gear and RAS system master cylinder. Hose failure resulting with hydraulic loss, may cause unexpected changes in steering effort and loss control of vehicle, potentially risk of crash.

Temsa is conducting a recall. With a service bulletin; the hydraulic hoses will be replaced with new ones and the routing will be checked. The recall work will be provided at no cost to you. Temsa estimates that it will take 2 hours to inspect and repair each affected vehicle. Temsa records indicate that you are the owner or operator of the following vehicle(s) included in this recall:

>>Units\_Number<<

Temsa strongly urges you to have the recall work performed on your vehicle(s) as quickly as possible. You may contact Temsa North America, Inc. at +1 833 628 36 72 if you have any questions about this recall campaign.

If you had this repair performed before you received this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy of the problem associated with this recall. For more information contact Temsa North America, Inc. at +1 833 628 36 72.

TEMSA ULAŖIM ARAÇLARI  
SANAYİ VE TİCARET A.Ŗ.

ADANA FABRİKA  
Sarıhamzalı Mahallesi,  
Turhan Cemal Beriker Bulvarı,  
No :563/A 01110 Seyhan /Adana  
T +90 322 441 02 26  
F +90 322 441 08 74  
info@temsa.com  
www.temsa.com

Mersis No: 0838004674900010  
Yüreğir V.D / 8380046749



If you have sold or otherwise transferred the vehicle(s) identified above, please contact Temsa North America, Inc. at +1 833 628 36 72 with all of the information you have regarding the current owner/operator of the vehicle(s).

Federal law requires any lessor who receives a notification of a determination of a safety related defect or noncompliance pertaining to any leased motor vehicle shall send the notice to the lessee within 10 days.

After contacting Temsa North America, Inc., if you are still not able to have the noncompliance remedied without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington DC. 20590 or call 1-888-327-4236 (TTY: 1-800-424-9153); or go to [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

We regret the inconvenience this may cause you, but urge you to implement the recall procedures with respect to your vehicle(s) as soon as possible for your added safety and satisfaction.

Sincerely,

İbrahim Eserce  
Chief Technology Officer

Osman Dundar  
R&D Manager