

## Creaking noises from lateral support bladder of cushion

Topic number	LI91.10-P-047382
Version	2
Design group	91.10 Front seats
Date	07-10-2014
Validity	Model series 221 facelift with dynamic seat (SA code 432) up to VIN 221...A290272
Reason for change	Damage code added
Reason for block	

### Complaint:

Creaking noises can occur when the side bolster bladders are inflated and deflated

### Cause:

Movement between felt panel and cushion shell.

### Remedy:

- Move seat concerned to foremost position.
- Remove side cover.
- Detach seat cushion cover at side and only fold up on door side.
- Cut (or assemble) 4 felt strips measuring 25 mm x 80 mm x 1 mm and glue on (for position, see PIC 01).
- Reassemble seat in reverse order.

Attachments	
File	Description
PIC 01.jpg	Position of felt strips

Symptoms
Body / Seat / Seat noises / Grunting
Body / Seat / Multicontour seat / Noise
Body / Seat / Seat noises / Creaking
Body / Seat / Dynamic multicontour seat / Noise

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other make part
A0009837110			Felt strip	1	15 mm x 1 mm Material bought by the meter Quantity as required		X

Work units				
Op. no.	Operation text	Time	Damage code	Note
			91N37 36	Right front seat cushion frame - noises
			91A37 36	Left front seat cushion frame - noises

Validity		
Vehicle	Engine	Transmission
221.022	*	*
221.028	*	*
221.054	*	*
221.056	*	*
221.070	*	*
221.071	*	*
221.077	*	*
221.080	*	*
221.084	*	*
221.086	*	*
221.087	*	*
221.095	*	*
221.122	*	*
221.128	*	*
221.154	*	*
221.156	*	*
221.170	*	*
221.171	*	*
221.176	*	*
221.177	*	*
221.179	*	*
221.180	*	*
221.184	*	*
221.186	*	*
221.187	*	*
221.195	*	*

Full model designation breakdown		
Vehicle	Engine	Transmission
221.022	642.930	722.902
221.028	629.911	722.903

221.054	272.946	722.999
221.056	272.965	722.906
221.070	273.922	722.904
221.071	273.961	722.904
221.077	156.984	722.907
221.077	156.984	722.930
221.080	642.932	722.962
221.084	273.924	722.961
221.086	273.968	722.961
221.087	272.975	722.960
221.095	272.974	722.950
221.122	642.930	722.902
221.128	629.911	722.903
221.154	272.946	722.999
221.156	272.965	722.906
221.170	273.922	722.904
221.171	273.961	722.904
221.176	275.953	722.649
221.177	156.984	722.907
221.177	156.984	722.930
221.179	275.982	722.649
221.180	642.932	722.962
221.184	273.924	722.961
221.186	273.968	722.961
221.187	272.975	722.960
221.195	272.974	722.950

Attachments

PIC 01.jpg:

