



## 2008 – 2009 Jetta



Volkswagen

Engine	Part	Part Number	Quantity
<b>2.0L FSI Turbo: BPY</b>	Oil Filter	06D-115-562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	4.6L (4.9qt)
	Drain Plug + Gasket	N-90813202	1
	Pollen Filter (20K Only)	1K1-819-653-B	1
<b>Miscellaneous</b>	Air Filter	06F-133-843-A	1
	Driver's Wiper Blade (>>D – 11.12.2005)	1K1-955-425-A-03C	1
	Passenger's Wiper Blade (>>D - 11.12.2005)	1K1-955-426-A-03C	1
	Wiper Blade Set	1Q1998002	1

Engine	Part	Part Number	Quantity
<b>2.0L TSI Turbo: CCTA, CBFA</b>	Oil Filter	06J-115-403-Q	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	4.6L (4.9qt)
	Drain Plug Gasket	See Tech Tip 17-12-02 Elsa Doc #2030603	1
	Pollen Filter (20K Only)	1K1-819-653-B	1
<b>Miscellaneous</b>	Air Filter	1K0-129-620-D	1
	Driver's Wiper Blade (>>D – 11.12.2005)	1K1-955-425-A-03C	1
	Passenger's Wiper Blade (>>D - 11.12.2005)	1K1-955-426-A-03C	1
	Wiper Blade Set	1Q1998002	1



## 2008 – 2009 Jetta



Volkswagen

Engine	Part	Part Number	Quantity
<b>2.0L Turbo Diesel: CBEA</b>	Oil Filter	071-115-562-C	1
	VW 507 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	4.0L (4.2qt)
	Drain Plug Gasket	N-90813202	1
	Pollen Filter (20K Only)	1K1-819-653-B	1
	Fuel Filter (20K Only) >>D – 08.02.2010 D – 09.02.2010>>	1K0127434A 1K0127434B	1
<b>Miscellaneous</b>	Air Filter	1K0-129-620-E	1
	Driver's Wiper Blade (>>D – 11.12.2005)	1K1-955-425-A-03C	1
	Passenger's Wiper Blade (>>D - 11.12.2005)	1K1-955-426-A-03C	1
	Wiper Blade Set	1Q1998002	1

Engine	Part	Part Number	Quantity
<b>2.5L 5 Cylinder: CBTA, CBUA</b>	Oil Filter	06D-115-562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	6.0L (6.3qt)
	Drain Plug + Gasket	N-90813202	1
	Pollen Filter (20K Only)	1K1-819-653-B	1
<b>Miscellaneous</b>	Air Filter	07K-129-620	1
	Driver's Wiper Blade (>>D – 11.12.2005)	1K1-955-425-A-03C	1
	Passenger's Wiper Blade (>>D - 11.12.2005)	1K1-955-426-A-03C	1
	Wiper Blade Set	1Q1998002	1

2008-2009	Engine Code		Torque Spec
<b>Oil drain plug Torque</b>	2.0L	BPY	30 Nm
	2.0L	CCTA,CBFA	
	2.0L TDI	CBEA	
	2.5L	CBTA, CBUA	
<b>Wheel hub bolt Torque</b>	2.0L	BPY	120 Nm
	2.0L	CCTA,CBFA	
	2.0L TDI	CBEA	
	2.5L	CBTA, CBUA	

Revised 11/11/2019

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



## 2008 – 2009 Jetta



Volkswagen

### 2009 Jetta Service Reminder Reset

#### Resetting the service interval display

If the schedule maintenance service was not done by a Volkswagen dealer, the service interval display function must be reset as follows:

- With the ignition off, press and hold the **0.0** trip odometer reset button.
- Switch the ignition on. The service interval function is now in reset mode.
- Let go of the **0.0** button and, within 20 seconds, briefly press the **m** clock reset button
- After a short time, the screen switches back to the normal display. The reset mode is cancelled if the **m** button is not pressed within 20 seconds, or if the vehicle is driven before resetting is complete.

#### Tips

- Do **not** reset the service interval function between scheduled maintenance intervals; doing so will result in an incorrect display.
- There are different instrument clusters for different models. Equipment and displays may vary.