






MPD UPDATE

Powertrain



	19 & 20MY I-PACE
<p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - High Voltage Battery State of Charge is below 10% after 120 or 150 day maintenance <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - High Voltage Battery State of Charge is below 10% after 120 or 150 day maintenance <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Diagnose any high voltage system related codes as per TOPlx. Follow guided diagnostics as required. If no root cause is found, please raise a Technical Assistance case for further support 	
KPI's	
Total VIN Count	Status
	
<p>  Solution Unavailable or project not yet accepted  Solution known, not yet delivered  Service Fix Available, Communication Published </p>	

