



Bulletin No.: PIP5700

Published date: N/A

Preliminary Information

PIP5700 8L45 8L90 Internal Wiring Harness Part Numbers By Application

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Cadillac	ATS Models	2016 - 2019	All	All	All	M5N M5T M5U
Cadillac	CT4 Models	2020	All	All	All	M5N
Cadillac	CT6	2016 - 2018	All	All	All	M5N M5X
Cadillac	CTS Models	2016 - 2019	All	All	All	M5N M5U
Cadillac	Escalade Models	2015 - 2017	All	All	All	M5U
Chevrolet	Camaro	2016 - 2020	All	All	All	M5T M5U
Chevrolet	Colorado	2017 - 2020	All	All	All	M5T
Chevrolet	Corvette	2015 - 2019	All	All	All	M5U
Chevrolet	Express	2017 - 2020	All	All	All	M5U
Chevrolet	Silverado	2015 - 2018	All	All	All	M5U M5X
Chevrolet	Silverado 1500 Mew Model	2019	All	All	All	MQE
Chevrolet	Silverado 1500	2020	All	All	All	MQE
GMC	Canyon	2017 - 2020	All	All	All	M5T
GMC	Savana	2017 - 2020	All	All	All	M5U
GMC	Sierra	2015 - 2018	All	All	All	M5U M5X
GMC	Sierra 1500 New Model	2019	All	All	All	MQE
GMC	Sierra 1500	2020	All	All	All	MQE

Involved Region or Country	North America
Condition	Some customers may comment on the operation or performance of the 8L45 or 8L90 transmission.
Cause	<p>Diagnostics may lead to the replacement of the transmission internal wiring harnesses.</p> <p>At this time the part numbers for the 2 piece harness are not available in the Electronic Parts Catalog.</p>


Correction:

Please refer to following information to obtain the part numbers for the transmission internal harnesses by application.


Note: One piece wiring harnesses are no longer available.

Please refer to the following pictures to aid in determining which internal mode switch is installed in the vehicle you are working on.

Example of a 10 pin internal mode switch.




Example of a 4 pin internal harness connector.



Example of a 4 pin internal mode switch.



Example of a 4 pin internal harness connector.



Parts Information

Description	Part Number	QTY
Pass Thru Harness With 10 Pin IMS Non-ESS	24297371	1
Valve Body Harness With 10 Pin IMS Non-ESS	24298757	1
Pass Thru Harness With 10 or 4 Pin IMS With ESS	24298759	1

Valve Body Harness With 10 Pin IMS With ESS	24298757	1
Pass Thru Harness With 4 Pin IMS Non-ESS	24297371	1
Valve Body Harness With 4 Pin IMS Non-ESS	24298758	1
Pass Thru Harness With 4 Pin IMS With ESS	24297372 (24298759 may be used if 24297372 is not available)	1
Valve Body Harness With 4 Pin IMS With ESS	24298758	1

Additional SI Keywords

P0711, P0712, P0713,

Version History

Version	1
Modified	01/14/2020 - Created on.



© 2020 General Motors. All Rights Reserved.