

Bulletin No.: PIC6389A Published date: 03/12/2020

Preliminary Information

PIC6389A Long Range Radar (LRR) Part Restriction

<u>Models</u>

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions:
			from	to	Engine:	Transmissions:
Cadillac	CT4	2020	All	All	All	All
Cadillac	CT5	2020	All	All	All	All
Involved Regior	or Country	North America				
Condition		As part of our ongoing continuous improvement we have placed the Long Range Radar Module used in the 2020 Cadillac CT4, and CT5 on restriction. If you believe a new module is needed, contact the PQC . Please have the part number available prior to contacting PQC. Please contact PQC by opening a new case via Dealer Case Management (DCM) From the DCM home page, click on "New PQC Case" found on the Technical Assistance tab.				
		Then in Global Connect click on the Support/Chat tab, TAC-PQC Tab, PQC -Parts Restrictions Templates to Download the appropriate PQC -Parts Restrictions Template and save a copy to your computer, You can attach a copy of the template to your PQC Case.				
		Note: (Do Not clear any DTCs prior to contacting the PQC).				
Cause		Root Cause Analysis				

Parts Information

Description	Part Number	Quantity
Long Range Radar	84712704	1

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
-----------------	-------------	------------

6620180	Forward Range Radar Sensor) Long Range	Use Published Labor Time
	Radar Replacement	

Version History

Version	2
Man al (Canad	01/13/2020 - Created on. 03/12/2020 - Added CT4



GENERAL MOTORS

© 2020 General Motors. All Rights Reserved.