

FT4830R1 Hanover Destination Sign Controller Electric Terminal Failures

Technical writer name

Yuvaraj

Manual section

13

| First Level Parts (100% of 26 vehicles) | | |
|---|-------------|--------|
| Material | Part Number | QTY |
| SUPPORT ODK HANOVER | N98591 | 1 |
| MOUNT FIR TREE CABLE TIE | N69081 | 2 |
| SCREW MSX20 R/C CR B633 TYPEVI | N17320 | 3 |
| WASHER FLAT OVS M5 ZP DIN9021 | N20687 | 3 |
| NUT M5 LOCKNYL YZ TRIV 96H CL5 | N11184 | 3 |
| TAPE FOAM 1"WIDTH X 1/8"THICK | N17210 | 0.27 m |
| TAPE NEOPRENE 1/4"W X 1/8"T | N30950 | 60 mm |

Note:
N17210 (TAPE FOAM 1"WIDTH X 1/8"THICK)
 1 ea = 100 ft ou 30.48m
 0.27 m / bus = 0.89 ft
 23.14ft for 26 buses
 1 pc for entire campaign

N30950 (TAPE NEOPRENE 1/4"W X 1/8"T)
 1 ea = 1 ft = 304.8 mm
 60 mm / bus
 1560 mm for 26 buses
 6 PC for entire campaign

| | |
|------------------|--------|
| Nb hours Level 1 | 0.7 hr |
|------------------|--------|

| | |
|-----|-----------|
| MQR | 7621-1856 |
|-----|-----------|

| Disposal of parts | | |
|--------------------|----------|---|
| Removed parts are: | | When the retained check box is check, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed, |
| Discarded | Retained | |
| X | - | |

| Second Level Parts (20% of 26 vehicles) | | |
|---|-------------|-----|
| Material | Part Number | QTY |
| CABLE EG3 POWER/COMMS STANDARD | N94088 | 5 |

| Second Level Parts (8% of 26 vehicles) | | |
|--|-------------|-----|
| Material | Part Number | QTY |
| CABLE ETHERNET M12D/RJ45 15FT | N91471-15 | 2 |

| Client | Order | Road numbers | | VIN | | QTY | Lang. | Customer | Target market | Plant | Config moteur | Model | NR | R1 | R2 |
|--|-------|--------------|------|---------------|---------------|-----|-------|----------|---------------|-------|---------------|-------|----|----|----|
| Chicago Transit Authority - CTA - Illinois | LB58 | 8325 | 8349 | L82J7J9776906 | L82J8J9776946 | 25 | E | US-Prv | US | PLB | TD | 40 | X | X | |
| Demo - Chicago Transit Authority - CTA | LC53 | — | — | L82J4K9777268 | L82J4K9777268 | 1 | E | US-Prv | US | PLB | TD | 40 | X | X | |