



HYUNDAI Technical Service Bulletin

GROUP

Body

NUMBER

20-BD-007H-1

DATE

May, 2020

MODEL(S)

All

SUBJECT:

CHEMICAL DISINFECTANT GUIDELINES

This TSB supersedes 20-BD-007H by including exterior surfaces and additional recommended products.

Description: This bulletin describes the general guidelines to help disinfect and protect vehicle exterior/interior surfaces using recommended safe chemical products.



Applicable Vehicles: All

CAUTION

Follow the guidelines from the Centers for Disease Control and Prevention (CDC) and the Occupational Safety and Health Administration (OSHA) for required personal protective equipment (PPE) and proper disinfecting procedures.

- The following chemical products are recommended to use for disinfecting vehicle exterior/interior surfaces from viruses and/or bacteria (including but not limited to: COVID-19 & influenza virus):

PRODUCT NAME	PART NUMBER	PRODUCT SIZE	IMAGE
Bioesque Botanical Disinfectant Solution	00232-19093	32 oz. spray bottle	
	00232-19094	1 gal. bottle	
	00232-19095	5 gal. pail	
Isopropyl Alcohol (minimum 70%)	N/A	N/A	

NOTE: Isopropyl Alcohol can be purchased at online retailer (Amazon/eBay).

Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

- Hydrogen peroxide, bleach, and ammonia based cleaners are NOT advised due to their strong toxic chemical structure and exothermic properties and may damage exterior/interior surfaces.
- Isopropyl alcohol products tend to quickly dry organic materials, which may result in leather surfaces appearing dry or faded.
 - Leather conditioner products are recommended to replenish the surface structure and maintain proper finish after disinfecting with isopropyl alcohol.
 - Some examples of leather conditioner products include:

Meguiar's Gold Class Leather Conditioner	Chemical Guys Leather Conditioner	Mother's Leather Conditioner
		

- Follow the manufacturer's instructions for all cleaning and disinfectant products that are not recommended in this bulletin.
- Disinfect commonly touched areas, including but not limited to:

Interior Surfaces

- | | |
|---|--|
| <ul style="list-style-type: none"> ○ Inside door handles ○ Interior door panels ○ Window and door lock controls ○ Dashboard ○ Steering wheel ○ Wiper and turn signal controls ○ Multimedia touch screens | <ul style="list-style-type: none"> ○ Multimedia and A/C controls ○ Shift lever/buttons ○ Center console controls ○ Center console armrest and storage ○ Cupholders ○ Glovebox ○ Seats and seat belt |
|---|--|

Exterior Surfaces

- | | |
|---|--|
| <ul style="list-style-type: none"> ○ Outside door handles ○ Trunk/tailgate release handle/button ○ Trunk/tailgate closing handle | <ul style="list-style-type: none"> ○ Trunk lid surfaces ○ Fuel filler door and fuel filler cap |
|---|--|