

Classification:

Reference:

Date:

BT17-016b

ITB17-043b

May 28, 2020

MOTION ACTIVATED LIFTGATE STICKER

APPLIED VEHICLES: 2017-2018 QX60 (L50) (with deluxe technology package)
 2017-2018 QX60 Hybrid (L50) (with deluxe technology package)

This bulletin is no longer applicable.

Discard previous versions of ITB17-043.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
July 24, 2017	ITB17-043	Original bulletin published
January 26, 2018	ITB17-043a	APPLIED VEHICLES and PARTS INFORMATION revised
May 28, 2020	ITB17-043b	Bulletin no longer applicable

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.