TECHNICAL NEWS 209

TRIUMPH 🐺

-Notice Information		
Ref	15301	
Posted Date:		
Posted To:	General Manager / Business Owner, Technician, Service Leader / Advisor, Accounts / Admin	
Subject:	Service/Technical	

TOL NOTICE (US&CA) - July 10, 2020

TOL Ref. # 15301-SVC

TECHNICAL NEWS 209

Technical News 209 is now available for download on the Triumph Technical News library located at **Triumph Online > Service/Technical > Technical News** or you can consult the attached **Technical News 209** PDF. Please ensure your workshops and all relevant staff are aware of the contents and any absent staff are informed upon their return. Please also update your workshop service manuals, procedures and have a printed copy available where appropriate.

Technical News 209			
ltem	Subject	Model Affected	
209.1	Riding Modes - Instrument Calibration Update	Street Triple R and Street Triple R-LRH from VIN 982752 up to VIN AC0897	
209.2	Pin Point Test - Manifold Absolute Pressure (MAP) Sensor	Rocket 3 R, Rocket 3 GT, Rocket 3 TFC	
209.3	Front Fork Tightening Sequence (incorporating Fork Top Caps and Directional Indicators)	Rocket 3 GT, Rocket 3 R, Rocket 3 TFC	
209.4	Electronic Systems Commissioning and Motorcycle Unlocking	Scrambler 1200 XC, Scrambler 1200 XE, Scrambler 1200 Bond Edition	
209.5	Electronic Systems Commissioning and Motorcycle Unlocking	Tiger 900, Tiger 900 GT, Tiger 900 GT-LRH, Tiger 900 GT Pro, Tiger 900 Rally, Tiger 900 Rally Pro	

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.