

GPOP - Issue Review System

Part Number: 04721896A\$

Part Description: Cooler line, Power steering return

Issue Description: The clips that hold the line to the core support are not available at this time and will need to be reused. Use care when opening and re-latching clip.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
