Mazda North American Operations Irvine, CA 92618-2922



Subject: MAZDA CONNECT HOT TEMPERATURE WARNING MESSAGE	M-Tips No.: MT-006/20
	Last Issued: 11/18/2020

BULLETIN NOTES

This M-Tip supersedes the previously issued M-Tip(s) listed below: The changes are noted in Red.

Previous M-Tips:	Date(s) Issued:	
MT-015/17	07/26/2017	
MT-018/14	2014	

APPLICABLE MODEL(S)/VINS

2016-2018 Mazda2	2016- <mark>2021</mark> CX-3	2016- <mark>2020</mark> MX-5
2014-2018 Mazda3	2016- <mark>2020</mark> CX-5	
2014- <mark>2021</mark> Mazda6	2016-2020 CX-9	

DESCRIPTION

Some customers may complain about the following MAZDA CONNECT™ Temperature Warning message:

• Display is too Hot. Screen performance may be decreased until it cools.

The warning message displays when the MAZDA CONNECT[™] screen temperature is above 176 degrees Fahrenheit (80 degrees Celsius).

Page 1 of 2

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication.

To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com. All contributions become property of MNAO, which assumes permission to publish them without further consideration.

© 2020 Mazda North American Operations, U.S.A.



This is a normal screen protection function. **Do not perform repairs for this concern.** Normal screen operation will resume when the screen temperature cools.

Page 2 of 2

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication.

To contribute repair tip ideas, send an e-mail to mtips@mazdausa.com. All contributions become property of MNAO, which assumes permission to publish them without further consideration.

© 2020 Mazda North American Operations, U.S.A.

11/19/2020 4:06 PM tlawrenc