



Ferrari North America Technical Information

Date: January 2021
Bulletin #: 2731
Campaign #:
Supersedes:
Section: 8

Model:   
  

Subject: Warranty Start Date and Brake Fluid Wear Reset DEIS Cycle

Please note that whenever a new vehicle is handed over to a customer, the **Warranty Start Date** must always be entered into the system following the procedure described in paragraph 2.3.1 of the **Aftersales Procedure Manual**.

For the models subject to this Technical Information, in addition to the entering the **Warranty Start Date**, the **DEIS cycle**

- **“NQS brake fluid change service reset”** must also be performed upon delivery of the new vehicle.

This reset procedure is necessary in order for the services related to the maintenance of the aforementioned models to function correctly.

Thank you for your co-operation.