

TECHNICAL NEWS 212



Notice Information

Ref	17126
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CA) - January 14, 2021

TOL Ref. # 17126-SVC

TECHNICAL NEWS 212

Technical News 212 is now available for download on the Triumph Technical News library located at [Triumph Online > Service/Technical > Technical News](#) or you can consult the attached [Technical News 212](#) PDF. Please ensure your workshops and all relevant staff are aware of the contents and any absent staff are informed upon their return. Please also update your workshop service manuals, procedures and have a printed copy available where appropriate.

Technical News 212		
Item	Subject	Model Affected
212.1	Triumph Diagnostic Tool Compatibility with Windows Operating Systems	Not Applicable
212.2	Triumph Diagnostic Tool (TDT) - Enable Connectivity System Process Update	Rocket 3 GT, Rocket 3 R, Rocket 3 TFC, Scrambler 1200 XC, Scrambler 1200 XE, Scrambler 1200 Bond Edition, Street Triple R and Street Triple R-LRH from VIN 806646 to VIN 982751, Street Triple RS (all VINs), Tiger XRX, Tiger XRX-LRH, Tiger XRT, Tiger XCX, Tiger XCA, Tiger 900 GT, Tiger 900 GT-LRH, Tiger 900 GT Pro, Tiger 900 Rally, Tiger 900 Rally Pro
212.3	Electronic Systems Commissioning and Motorcycle Unlocking	Trident 660
212.4	Electronic Systems Commissioning and Motorcycle Unlocking	Tiger 850 Sport, Tiger 900, Tiger 900 GT, Tiger 900 GT-LRH, Tiger 900 GT Pro, Tiger 900 Rally, Tiger 900 Rally Pro

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.

