



## SPYDER 2012 Low Fuel Level Light Always On - 138572

[Printable Version](#)

Rate This Article

(Average Rating: 3.92)

Version 1

Language English ▼

[Show Properties](#)**Summary:**

The low fuel level light indicator stay always ON after cluster replacement on MY12 RT.

**Type:**

General

**TST Detail:****Problem:**

The low fuel level light indicator stay always ON after cluster replacement on MY12 RT. Production cluster P/N is 710002975 works fine with the analog gauge but the new superseded cluster P/N creates that low fuel light problem due to a variation in the low fuel circuit on the new clusters. Everything works as it should if you unplug the analog fuel gauge.

**Solution:**

Install the latest analog fuel gauge P/N 710004207 installed on MY13 & up.

**Warranty:**

NA

**Attachment:**

**First Published By:** Eric Fauteux on 2021-03-15

**Last Modified By:** Eric Fauteux on 2021-03-15