TECHNICAL TOPICS ELECTRICAL





16 – 21MY E PACE, F PACE, I PACE, F TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport, & Defender equipped with InControl Touch Pro or Pivi

Activity	Purpose	Vehicles	Completion	Notes
H251 & N377 - InControl Touch Pro Updates	To update InControl Touch Provehicles to the latest IMC software level, and to enable SOTA updates moving forward.	16–18MY Cross Car Line	LR 77% completed +1% Jag 81% completed +1%	Update performed via Pathfinder / SDD at retailer to bring the vehicle to a SOTA capable level. NDU for SDD was released on 3-Sep-20
IMC 20C1 Software Release	Provide additional bug fixes and infotainment stability 20C1 –Resolve X152 & X351missing InControl Apps & RSE SOTA improvements	16-20MY Cross Car Line	41,752 Successful Updates	20C1 supersedes 20C 15-Jan-21
TCU ∨19.2	Provide additional stability for SOTA updates and resolve Remote App concerns.	16-20MY Cross Car Line	12,826 Customer Updates 3,881 Updates via TOPIx	Customer Update for TCU v18.2 TOPIX Update for TCU v14.2 – Fix on Fail
Pivi IP27.2 (OS 2.0.6)	Latest update for Pivi to provide improvements and address known issues.	20MY L663 Defender 21MY Cross Car Line	8,153 Successful Updates	OS 2.0.6 Launched on 27-Nov-20 IP30 to launch on 25-Mar-21









