

SERVICE BULLETIN

Classification: AN12-043D Reference:

ITB12-041D

Date:

COPYRIGHT© NISSAN NORTH AMERICA, INC.

March 11, 2021

SIRIUSXM SATELLITE RADIO / WEATHER / TRAFFIC / TRAVEL LINK ACTIVATION

This bulletin has been amended. See AMENDMENT HISTORY on the last page. Discard all previous versions of this bulletin.

APPLIED VEHICLES:

2011-2015 Infiniti vehicles

SERVICE INFORMATION

If a customer would like to activate a subscription for any of the following services:

- SiriusXM satellite radio
- NavTraffic
- NavWeather
- Travel Link (fuel prices, stocks, sports scores, movies listings, weather)
- 1. Review the Service Availability chart on page 2 to confirm the vehicle is properly equipped for the service.
- 2. If properly equipped, perform the Satellite Radio / Weather / Traffic / Travel Link activation procedure on page 2.

If a radio is replaced for any reason, and a customer has an active subscription to any of the above services:

- Contact SiriusXM Dealer Support toll-free at 1-800-852-9696 to update the subscription information. The new SiriusXM Radio ID (see steps 1-4 on page 2), VIN, and customer name will be requested during the call.
- 2. Perform the Satellite Radio / Weather / Traffic / Travel Link Activation procedure on page 2.

<u> 0R</u>

If a customer claims to have an active subscription to any of the above services, AND any portion of the subscribed service is not operating:

- 1. Contact SiriusXM Dealer Support toll-free at 1-800-852-9696 to confirm the subscription(s) is active.
- 2. If the subscription(s) is confirmed, perform the **Satellite Radio / Weather / Traffic / Travel Link** activation procedure on page 2.

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti dealer to determine if this applies to your vehicle.

NOTE: Before attempting to activate a subscription for satellite radio, NavTraffic, or NavWeather, review the service availability chart below to confirm the vehicle is properly equipped for the service.

Vehicle	Satellite Radio	NavTraffic	NavWeather	Travel Link
EX / QX50	S	NAVI	NAVI	N/A
FX / QX70	S	NAVI	NAVI	N/A
G / Q60	S	NAVI	NAVI	N/A
JX / QX60	S	NAVI	NAVI	N/A
M / Q70	S	NAVI	NAVI	N/A
QX / QX80	S	S	S	N/A
Q50	S	NAVI	N/A	S
Q40	S	NAVI	NAVI	N/A

Service Availability

S Standard. Vehicle is properly equipped.

- **NAVI** Properly equipped if vehicle has Navigation System.
- N/A Not available

NOTE: All vehicles are factory activated, which means they will arrive on your lot fully functional. The demo service will automatically convert to a consumer account with a three-month trial via the Retail Delivery Record process. Therefore, if the vehicle was properly factory activated or refreshed upon receipt, there is NO FURTHER ACTION REQUIRED of the sales consultant to activate satellite radio / NavTraffic / NavWeather / Travel Link (as applicable) for the customer.

Satellite Radio / Weather / Traffic / Travel Link Activation

- 1. Park the vehicle outside.
- 2. Turn ON the engine.
- 3. Turn ON the radio and tune to channel "O" on the SiriusXM source.
- 4. Write down the 8-digit SiriusXM Radio ID displayed on the screen.
- 5. Tune to channel "1" on the SiriusXM source and leave ON the radio.
- 6. If activating/refreshing NavTraffic and/or NavWeather, press the **INFO** button and select **Traffic Info** or **Weather Info** to display the respective screen.

- 7. Activate/refresh service at <u>www.siriusxm.com/refresh</u> or by calling SiriusXM Dealer Support toll-free at 1-800-852-9696.
- 8. The service should be activated/refreshed within 30 minutes.
 - For satellite radio Audio will broadcast when tuned to channels other than "1".
 - For satellite traffic and/or weather Traffic/weather information will display on the Traffic Info/Weather Info screen.
 - For Travel Link Information will display any of the items on the SXM information screen.
- 9. Turn OFF the engine.
- 10. Wait 5 minutes.

NOTE: Do not disconnect the battery or pull any fuses during this time.

- 11. Turn ON the engine.
- 12. Re-check that the activated/refreshed service is operational.

For additional information or assistance, go to www.siriusxmdealer.com

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
July 24, 2012	ITB12-041	Original bulletin published
October 25, 2012	ITB17-041A	Bulletin amended to include info about updating subscriptions when replacing radio
November 1, 2013	ITB17-041B	Amended to add additional models
January 5, 2015	ITB17-041C	
March 11, 2021	ITB17-041D	Classification number updated