

Service Manager Bulletin

TITLE:

**Shipping and Handling of Polestar Lithium-ion Battery Electric Vehicle (BEV)
Battery Modules to Global Battery Solutions (GBS)**

GROUP:**31****NO:****004P****ISSUING DEPARTMENT:****Warranty****CAR MARKET:****Canada only****REVISIONS:****ISSUE DATE:****2021-03-17****STATUS DATE:****2021-04-16****Page 1 of 11**

Attention Polestar Parts Managers and Service Managers

There may come a time when a customer's vehicle will require technical service and you will be instructed to replace and ship a defective lithium battery electric vehicle (BEV) battery module directly to our supplier for technical evaluation.

For complete battery packs, please see SMB31-001.

Note: All Polestar Lithium-ion Battery Electric Vehicle (BEV) Batteries modules will be part of our Polestar Technical Helpdesk Prior Approval Process.

The failed battery electric vehicle (BEV) battery must be shipped directly to the Polestar Battery Center, operated by Global Battery Solutions (GBS), at the address indicated below and on the shipping labels attached.

POLESTAR LITHIUM-ION BATTERY ELECTRIC VEHICLE (BEV) BATTERY MODULE SHIPPING AND HANDLING GUIDELINES:

Remove the replacement module from its shipping box and follow instructions as outline in VIDA and/or provided by Retailer Technical Support (RTS) for installation.

HANDLING:

Ensure the replacement box and packaging are kept in their original condition. The replacement battery module shall be removed from its original packaging and installed in the vehicle as soon as possible in order to maintain protection against mechanical impact or tampering.

Once the replacement module is removed, store the shipping box in a safe and secure place to be used for the transportation of the defective battery electric vehicle (BEV) battery module.

- Do not remove or cover up any of the hazmat shipping labels on the outside of the replacement box.
- Do not damage or disassemble the replacement box.

Service Manager Bulletin 31-004P

- If you damage the box you will be charged for a replacement box plus shipping and hazmat labeling cost.

Before packaging the module, make sure that it has been emptied of all coolant and dried. It may be necessary to package the module with an absorbent towel to collect any remaining coolant.

Carefully place the defective battery electric vehicle (BEV) battery module inside of the bag it arrived in, then repackage the module with all included foam inside of the box. Reseal the box with packaging tape ensuring the warning labels on the package are not obscuring.

Warning labels “Class 9” and “Cargo Aircraft Only” must be present and unobscured on a minimum of two sides of the container.

It is mandatory the defective battery electric vehicle (BEV) battery module be shipped to GBS within 2 days of receiving the replacement battery module. The defective battery module must be received by GBS within 7 days of receipt of the replacement battery module.

SHIPPING:

All core shipments to the Battery Center must include a proper core report. Without the core report core credit will not be given. See the Core Return Procedure chapter in the Parts Policy and Procedure manual, found on the Retailer Portal, for instructions on how to create a core report and core packing list.

Please complete the attached FedEx VICS Bill of lading. Retailers only need to fill out their return address, RMA number and add the part number in the carrier information section.

Commercial Invoice

You will also need to print and complete the attached Commercial Invoice. Retailers only need to fill out the Exporter section (Contact Name:, Telephone No., E-Mail, Company Name/Address) as well as add the battery part number in the Description of Dangerous Goods field. Do not alter any information on this Commercial Invoice.

All other information is pre-filled. Do not alter any information on this Bill of lading.

Located at the end of this bulletin are 4 GBS return shipping labels pre-addressed to Global Battery Solutions.

- Cut out one of the labels.
- Fill out this label completely. Ensure the RMA Number is on the label.
- Secure the label to the outside of the replacement container.
- Contact the FedEx Freight at the number below and request a pick-up:
FedEx Freight Customer Service 1.866.393.4585

You must complete the attached Commercial Invoice. Retailers only need to fill out the Exporter section contact and address information. Retailers must also add the part number under the Description of Goods section.

Ship to:

Global Battery Solutions (GBS)
581 Ottawa Ave, Suite 100
Holland, MI 49423
Attention: Stacy Trott

Service Manager Bulletin 31-004P

Once the FedEx Driver arrives, it is important to give the driver the completed FedEx Bill of Lading and a copy of the Safety Data Sheet. You can print a copy of the Safety Data Sheet from SMB 31-006P.

You should also have attached a copy of the Safety Data Sheet to the outside of the replacement shipping crate using the Polestar Poly Bags 7777601.

Warranty and Technical Documents

These documents must be included inside the box with the defective module.

- Technical Helpdesk Vehicle Report - (mandatory) see sample below.
- Shipping Label affix to the outside of the replacement box. (mandatory)
- Material Data Safety Sheets affix to the outside of the replacement crate. (mandatory)
- Copy of the original Repair order-see sample below

NOTE: Failure to include the above documents may result in the package being returned at retailer expense.

Package Example

PLEASE DO NOT COVER OR REMOVE ANY OF THE HAZMAT LABELS.

Service Manager Bulletin 31-004P

CUSTOMER #: 1234569

POLESTAR CANADA RETAILER

ONE POLESTAR DRIVE

SERVICE PH: 201-768-7300 · 201-768-4556

www.polestar.com

WARRANTY

PAGE 2

HOME:

CONT:N/A

BUS:

CELL:

SERVICE ADVISOR 56 John Wayne

COLOR	YEAR	MAKE/MODEL		VIN		LICENSE	MILEAGE IN / OUT		TAG
VOID BLACK	21	POLESTAR 2		LPSED3KA7ML012077			3000/3099		
TYPE	DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
IS				16:30 15JAN21		0.00	CASH	26JAN21	
DD									
R.O. OPENED		READY		OPTIONS: STK:E054916 ENG:BEV TRN:AUTO					

07:26 15JAN21 13:40 26JAN21

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
FOUND MESSAGE BECAME PRESENT FOR CHARGING SYSTEM FAILURE, ATTEMPTED TO CHARGE IN "SAVE" MODE AND MESSAGE WAS DISPLAYED FOR CHARGING SYSTEM FAILURE. FAULT TRACED PER CSC "YL". CHECKED DTCs AND FOUND BECM-P0DBF00 STORED. FAULT TRACED AND FOUND LIKELY CAUSE IS INTERNAL FAULT IN HV BATTERY CELL "E". CONTACTED THD PER CASE RE #1234567. ASSISTED THD WITH REMOTE DIAGNOSTICS, ATTEMPTED BECM RELOAD, BATTERY RESETS AND OTHER DIAGNOSTICS TO RESTORE CELL BALANCING. ALL ATTEMPTS FAILED TO RESOLVE CONCERN. PER THD, REPLACED HV BATTERY AND PERFORMED BECM RELOAD. CLEARED DTCs AND TESTED CHARGING. CHARGING NOW FUNCTIONS BUT LEDs AT CHARGING OUTLET DO NOT LIGHT OR GIVE ANY INDICATION. FAULT TRACED PER CSC "YW". FAULT TRACED LED FAULT. DISCONNECTED MANUAL SERVICE DISCONNECT AND REMOVED LF FENDER LINING TO EXPOSE CHARGING OUTLET. INSPECTED OUTLET AND FOUND CONNECTOR HAS BEEN PULLED OUT OF LED PORTION OF CHARGING OUTLET DUE TO ZIP TIE CAUSING TOO MUCH TENSION ON WIRING. REMOVED ZIP TIE AND SECURED CONNECTOR. CHECKED WIRING TO BE SURE WIRING DOES NOT HAVE EXCESSIVE MOVEMENT-OK. RESTORED HV MSD AND TESTED LEDs AND FOUND ALL CHARGING INDICATIONS ARE FUNCTIONING PROPERLY. TEST DROVE AND FOUND ALL FUNCTIONS ARE NOW OPERATIONAL.							

YOUR COMPLETE SATISFACTION IS OUR GOAL. IF FOR ANY REASON YOUR VISIT WAS NOT OUTSTANDING

WE APPRECIATE YOUR BUSINESS.

TECH: 00000 ACTUAL HRS.: 00.00 SOLD HRS.: 00.0

SALE-LBR: 0000.00 PTS: 0000.00 MSC: 0.00 LUB: 0.00 SUB: 0.00 TOTAL 00000
COST-LBR: 000.00 PTS: 0000.00 MSC: 0.00 LUB: 0.00 SUB: 0.00 TOTAL 00000

DATE	START	FINISH	DURATION	TYPE	TECH	LINE(S)	CHG
01-15-16	00:00	00:00	0.00	W	00000	A	
	00:00	00:00	0.00	W	00000	C	
	00:00	00:00	0.00	W	00000	B	
	00:00	00:00	0.00	W	00000	D	

[] CASH [] CHECK CK NO. []
[] VISA [] MASTER CARD [] DISCOVER
[] AMER XPRESS [] OTHER [] CHARGE

Thank You for Your Business!

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
ADJUSTMENT	
SUBLET AMOUNT	
SUPPLIES/WASTE DISP.	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

CUSTOMER SIGNATURE

PACKAGE EXAMPLE

- Use the original packaging replacement box
- Please ensure the original GBS Labels are clearly visible on the out side of the box
- All document must be included in a Warranty Polybag part number 7777601
- Do not cover or remove any of the Hazmat labels

From: _____

Global Battery Solutions (GBS)
581 Ottawa Ave, Suite 100
Holland, MI 49423
Attention: Stacy Trott

 **GLOBAL BATTERY SOLUTIONS**


RMA Number _____
TIE Report Number _____
FedEx Tracking Number _____



Service Manager Bulletin 31-004P

UNIFORM STRAIGHT BILL OF LADING ORIGINAL---NOT NEGOTIABLE

SUBJECT TO THE TERMS AND CONDITIONS OF THE UNIFORM BILL OF LADING --- QUESTIONS? CALL 1.866.393.4585

	Date	Purchase Order #					
	Shipper #	Shipper #					
	<div>REQUIRED: Please select a service type <input type="checkbox"/> FedEx Freight® Priority <input checked="" type="checkbox"/> FedEx Freight® Economy</div>						
		OPTIONAL: You may select a money-back guarantee delivery (charges and tariff limitations may apply). <input type="checkbox"/> A.M. Delivery <input type="checkbox"/> Close of Business Delivery					
SHIPPER (from) Please provide ZIP codes and phone numbers.				CONSIGNEE (to)			
Shipper		FXF Acct. #		Consignee		FXF Acct. #	
Attn. to		Area Code Phone Number		Attn. to		Area Code Phone Number	
Address				Address			
Address (Store, Dept., Ste., Flr., Apt., Div.)				Address (Store, Dept., Ste., Flr., Apt., Div.)			
Address				Address			
City				City			
State/Province		ZIP/Postal Code Country		State/Province		ZIP/Postal Code 49423 Country USA	
Optional or Additional Service Fees and Charges <input type="checkbox"/> Liftgate <input type="checkbox"/> Inside Pickup <input type="checkbox"/> Limited Access				Optional or Additional Service Fees and Charges <input type="checkbox"/> Liftgate <input type="checkbox"/> Inside Delivery <input type="checkbox"/> Limited Access			
Shipper Bill of Lading #				<input type="checkbox"/> Custom Delivery Window:			
Special Instructions							
For Clearance carrier must send documents to US Customs Broker: Expeditors, nbauto@expeditors.com							
BILL FREIGHT CHARGES TO (if different than above):							
Name		FXF Acct. #		Mailing Address			
POLESTAR AUTOMOTIVE USA INC. c/o Williams & Associates		FedEx ACCT# 673220215		405 E 78TH ST			
City		State		ZIP/Postal Code		Area Code Phone Number	
BLOOMINGTON		MN		55420 US		952 884-9959	
Freight charges are PREPAID unless marked collect.		<input type="checkbox"/> USD C.O.D. <input type="checkbox"/> CAD AMOUNT		1. The letters "C.O.D." must appear in box before consignee's name above. 2. C.O.D. funds to be collected as: <input type="checkbox"/> Certified Funds <input type="checkbox"/> Company Check <input type="checkbox"/> Personal Check 3. C.O.D. fee to be paid by: <input type="checkbox"/> Shipper <input type="checkbox"/> Consignee			
CHECK BOX IF COLLECT <input type="checkbox"/>							
REMIT C.O.D. TO (if different than shipper above):							
Name				Mailing Address			
City		State		ZIP/Postal Code		Country Code Area Code Phone Number	
<small>RECEIVED, subject to individually determined rates or contracts that have been agreed upon in writing between the carrier and shipper, if applicable, otherwise to the rates, classifications and rules that have been established by the carrier and are available to the shipper, on request, and to all applicable state and federal regulations, the property described below, in apparent good order, except as noted (contents and condition of contents of packages unknown) marked, consigned and destined as shown hereon, which said carrier agrees to carry to destination, if on its route, or otherwise to deliver to another carrier on the route to destination. Every service to be performed hereunder shall be subject to all the conditions not prohibited by law, whether printed or written, herein contained, including the conditions on the back hereof, and the conditions of the FXF 100 Series Rules Tariff, or otherwise referenced, which are hereby agreed to by the shipper and accepted for himself and his assigns.</small>							
HANDLING UNITS (H/U)	H/U PKG. TYPE	PIECES	HM (X)	KIND OF PACKAGE, DESCRIPTION OF ARTICLES, SPECIAL MARKS AND EXCEPTIONS (subject to correction)	WEIGHT IN LBS. (subject to correction)	NMFC ITEM #	CLASS CUBE
1	CTN	1	X	UN3480, LITHIUM ION BATTERIES, 9.11, EMERGENCY GUIDE #147	50.0 LBS	0606680-01	050
				Hazardous Material Package Type: Box			
				Box DIMS: 15 x 10.5 x 10.5 in.			
				Part Number:			
				DANGEROUS GOODS			
				DO NOT STACK PALLETS			
TOTAL H/U: 1		★ MARK "X" OR "RQ" IN THE HM COLUMN TO DESIGNATE HAZARDOUS MATERIALS OR REPORTABLE QUANTITY AS DEFINED IN DOT REGULATIONS.					
HM EMERGENCY CONTACT PHONE NUMBER (800) 535-5053				FOR INTERNATIONAL SHIPMENTS INDICATE BROKER NAME, FAX AND PHONE NUMBERS.			
CUSTOMER REGISTERED W/EMERGENCY RESPONSE INFO. PROVIDER or CONTRACT #				EEI/SED Number or Exception			
Volvo Car USA LLC - MIS0004316				Broker Name			
				Shipper Signature			
				SHIPPER CERTIFICATION			
				I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations.			
				Carrier acknowledges receipt of packages and required placards. Carrier certifies emergency response information was made available and/or carrier has the DOT emergency response guidebook or equivalent document in the vehicle.			
				DATE DRIVER/EMPLOYEE NUMBER PIECE COUNT TRAILER #			

Create your next Bill of Lading online at fedex.com/us/freight/main/

FedEx Freight

CO202/616-EXF 0023776PM

UNIFORM STRAIGHT BILL OF LADING Terms & Conditions

Sec. 1. (a) The carrier or the party in possession of any of the property described in this Bill of Lading shall be liable as at common law for any loss thereof or damage thereto, except as hereinafter provided.

(b) No carrier shall be liable for any loss or damage to a shipment or for any delay caused by an Act of God, the public enemy, the authority of law, or the act or default of shipper. Except in the case of negligence of the carrier or party in possession, the carrier or party in possession shall not be liable for loss, damage or delay which results: when the property is stopped and held in transit upon request of the shipper, owner or party entitled to make such requests; or from faulty or impassible highway, or by lack of capacity of a highway bridge or ferry; or from a defect or vice in the property; or from riots or strikes. The burden to prove freedom from negligence is on the carrier or the party in possession.

Sec. 2. Unless arranged or agreed upon, in writing, prior to shipment, carrier is not bound to transport a shipment by a particular schedule or in time for a particular market, but is responsible to transport with reasonable dispatch. In case of physical necessity, carrier may forward a shipment via another carrier.

Sec. 3. (a) As a condition precedent to recovery, claims must be filed in writing with: any participating carrier having sufficient information to identify the shipment.

(b) Claims for loss or damage must be filed within nine months after the delivery of the property (or, in the case of export traffic, within nine months after delivery at the port of export), except that claims for failure to make delivery must be filed within nine months after a reasonable time for delivery has elapsed.

(c) Suits for loss, damage, injury or delay shall be instituted against any carrier no later than two years and one day from the day when written notice is given by the carrier to the claimant that the carrier has disallowed the claim or any part or parts of the claim specified in the notice. Where claims are not filed or suits are not instituted thereon in accordance with the foregoing provisions, no carrier shall be liable, and such claims will not be paid.

(d) Any carrier or party liable for loss of or damage to any of said property shall have the full benefit of any insurance that may have been effected, upon or on account of said property, so far as this shall not avoid the policies or contracts of insurance, PROVIDED, that the carrier receiving the benefit of such insurance will reimburse the claimant for the premium paid on the insurance policy or contract.

Sec. 4. (a) If the consignee refuses the shipment tendered for delivery by carrier or if carrier is unable to deliver the shipment, because of fault or mistake of the consignor or consignee, the carrier's liability shall then become that of a warehouseman. Carrier shall promptly attempt to provide notice, by telephonic or electronic communication as provided on the face of the Bill of Lading, if so indicated, to the shipper or the party, if any, designated to receive notice on this Bill of Lading. Storage charges, based on carrier's tariff, shall start no sooner than the next business day following the attempted notification. Storage may be, at the carrier's option, in any location that provides reasonable protection against loss or damage. The carrier may place the shipment in public storage at the owner's expense and without liability to the carrier.

(b) If the carrier does not receive disposition instructions within 48 hours of the time of carrier's attempted first notification, carrier will attempt to issue a second and final confirmed notification. Such notice shall advise that if carrier does not receive disposition instructions within 10 days of that notification, carrier may offer the shipment for sale at a public auction and the carrier has the right to offer the shipment for sale. The amount of sale will be applied to the carrier's invoice for transportation, storage and other lawful charges. The owner will be responsible for the balance of charges not covered by the sale of the goods. If there is a balance remaining after all charges and expenses are paid, such balance will be paid to the owner of the property sold hereunder, upon claim and proof of ownership.

(c) Where carrier has attempted to follow the procedure set forth in subsections 4(a) and (b) above and the procedure provided in this section is not possible, nothing in this section shall be construed to abridge the right of the carrier at its option to sell the property under such circumstances and in such manner as may be authorized by law. When perishable goods cannot be delivered and disposition is not given within a reasonable time, the carrier may dispose of property to the best advantage.

(d) Where a carrier is directed by consignee or consignor to unload or deliver property at a particular location where consignor, consignee, or the agent of either, is not regularly located, the risk after unloading or delivery shall not be that of the carrier.

Sec. 5. (a) In all cases not prohibited by law, where a lower value than the actual value of the said property has been stated in writing by the shipper or has been agreed upon in writing as the released value of the property as determined by the classification or tariffs upon which the rate is based, such lower value plus freight charges if paid shall be the maximum recoverable amount for loss or damage, whether or not such loss or damage occurs from negligence.

(b) No carrier hereunder will carry or be liable in any way for any documents, coin money, or for any articles of extraordinary value not specifically rated in the published classification or tariffs unless a special agreement to do so and a stipulated value of the articles are endorsed on this bill of lading.

Sec. 6. Every party, whether principal or agent, who ships explosives or dangerous goods, without previous full written disclosure to the carrier of their nature, shall be liable for and indemnify the carrier against all loss or damage caused by such goods. Such goods may be warehoused at owner's risk and expense or destroyed without compensation.

Sec. 7. (a) The consignor or consignee shall be liable for the freight and other lawful charges accruing on the shipment, as billed or corrected, except that collect shipments may move without recourse to the consignor when the consignor so stipulates by signature or endorsement in the space provided on the face of the Bill of Lading. Nevertheless, the consignor shall remain liable for transportation charges where there has been an erroneous determination of the freight charges assessed, based upon incomplete or incorrect information provided by the consignor.

(b) Notwithstanding the provisions of subsection (a) above, the consignee's liability for payment of additional charges that may be found to be due after delivery shall be as specified by 49 U.S.C. §13706, except that the consignee need not provide the specified written notice to the delivering carrier if the consignee is a for-hire carrier.

(c) Nothing in this Bill of Lading shall limit the right of the carrier to require the prepayment or guarantee of the charges at the time of shipment or prior to delivery. If the description of articles or other information on this Bill of Lading is found to be incorrect or incomplete, the freight charges must be paid based upon the articles actually shipped.

Sec. 8. If this Bill of Lading is issued on the order of the shipper, or his agent, in exchange or in substitution for another Bill of Lading, the shipper's signature on the prior Bill of Lading or in connection with the prior Bill of Lading as to the statement of value or otherwise, or as to the election of common law or Bill of Lading liability shall be considered a part of this Bill of Lading as fully as if the same were written on or made in connection with this Bill of Lading.

Sec. 9. If all or any part of said property is carried by water over any part of said route, such water carriage shall be performed subject to the terms and provisions and limitations of liability specified by the "Carriage of Goods By Sea Act" and any other pertinent laws applicable to water carriers.

Service Manager Bulletin 31-004P

COMMERCIAL INVOICE

This invoice must be completed in English.

Page 1 of 1

EXPORTER: Tax ID#: EIN 105557987RM0001 Contact Name: Telephone No.: E-Mail: Company Name/Address: Country/Territory: Canada Parties to Transaction: <input checked="" type="checkbox"/> Related <input type="checkbox"/> Non-Related					Ship Date: Air Waybill No. / Tracking No.: Invoice No.: Purchase Order No.: Payment Terms: Bill of Lading: PREPAID FedEx Acct 673220215 Purpose of Shipment: OTHER (PLEASE SPECIFY) Used Defective Auto Part.				
CONSIGNEE: Tax ID#: EIN 47-490375000 Contact Name: Stacy Trott Telephone No.: 866-327-0318 E-Mail: strott@globalbatterysolutions.com Company Name/Address: Polestar Automotive USA Inc. Global Battery Solutions (GBS) 581 Ottawa Ave, Suite 100 Holland, MI 49423 Country/Territory: United States					SOLD TO / IMPORTER (if different from Consignee): <input type="checkbox"/> Same as CONSIGNEE: Tax ID#: SELECT DOWN ARROW FOR OPTIONS Company Name/Address: Country/Territory:				
If there is a designated broker for this shipment, please provide contact information. Name of Broker Expeditors Tel. No. 734-229-1758 Contact Name nbauto@expeditors.com									
Duties and Taxes Payable by <input type="checkbox"/> Exporter <input type="checkbox"/> Consignee <input checked="" type="checkbox"/> Other If Other, please specify Polestar Automotive USA c/o Williams & Associates ACCT# 673220215									
No. of Packages	No. of Units	Net Weight (LBS / KGS)	Unit of Measure	Description of Goods	Harmonized Tariff Number	Country of Manufacture	Unit Value	Total Value	
1	1	50.0	LBS	UN 3480, Lithium - ion Batteries.9.11 DANGEROUS GOODS Emergency Guide, 147 CLASS 9 Dimensions: 15" L X 10.5" W X 10.5" H	8538.90	KR	1,165.00	1,165.00	
							0.00	0.00	
							0.00	0.00	
							0.00	0.00	
Total Pkgs	Total Units	Total Net Weight	(Indicate LBS/KGS)	Total Gross Weight	(Indicate LBS/KGS)	Terms of Sale:	Subtotal:	1,165.00	
1	1	50	LBS	50	LBS	FCA=Free Carrier	Insurance:	0.00	
Special Instructions: EMERGENCY PHONE NUMBER - CONTACT: CHEMTREC - 800-424-9300 Declaration Statement(s):							Freight:	0.00	
							Packing:	0.00	
							Handling:	0.00	
							Other:	0.00	
I declare that all the information contained in this invoice to be true and correct.							Invoice Total:	1,165.00	
Originator or Name of Company Representative if the invoice is being completed on behalf of a company or individual:							Currency Code:	USD	
Signature / Title / Date:									

REV. 04.10.13-1.08

Polestar

[+ Follow](#)

Case
Vehicle would not move, zero battery level on display - LPSED3KA0ML009389

Priority
Medium

Status
Submitted

Case Number
0020073

SAMPLE VEHICLE REPORT

	DETAILS	RELATED ITEMS
▼ Retailer Information	Retailer Polestar Internal - Test Created By Customer Support_3/2/2021 11:23 AM	Retailer Code TEST23 Last Modified By Customer Support_3/2/2021 11:23 AM
▼ Case Information	Case Number 0020073 Subject Vehicle would not move, zero battery level on display - LPSED3KA0ML009389 Part Number 3225772 CSC N0 Concern Area Vehicle Report Part Available Part Available Fault Type Business Process	Record Type TIE Vehicle Report Status Submitted Retailer Comments Replace battery Function Group 0532 Sub Concern Area Support Needed DTC P55665 Urgent Yes

Post

Share an update...

Share

Search this feed...

Customer Support (Partner) updated this record.
Just now
 Case Owner (using assignment rule)
Customer Support to TIE Vehicle Report Queue

Like Comment

Write a comment...

Customer Support (Partner) created this case.
Just now
 0020073
View more details

Like Comment

From: _____

Global Battery Solutions (GBS)
581 Ottawa Ave, Suite 100
Holland, MI 49423
Attention: Stacy Trott



RMA Number _____

TIE Report Number _____

FedEx Tracking Number _____

From: _____

Global Battery Solutions (GBS)
581 Ottawa Ave, Suite 100
Holland, MI 49423
Attention: Stacy Trott



RMA Number _____

TIE Report Number _____

FedEx Tracking Number _____

From: _____

Global Battery Solutions (GBS)
581 Ottawa Ave, Suite 100
Holland, MI 49423
Attention: Stacy Trott



RMA Number _____

TIE Report Number _____

FedEx Tracking Number _____

From: _____

Global Battery Solutions (GBS)
581 Ottawa Ave, Suite 100
Holland, MI 49423
Attention: Stacy Trott



RMA Number _____

TIE Report Number _____

FedEx Tracking Number _____