

Bulletin No.: PIT5686B Published date: 05/25/2021

# **Preliminary Information**

# PIT5686B Adding or Installing a Rearview Camera

## <u>Models</u>

Brand:	Model:		Model Years:	VIN:		Engine	Transmissions:	
branu.				from	to	Engine:	Transmissions:	
Chevrolet	Silverado 4500HD, 5500HD, 6500HD		2019 - 2021	All	All	All	All	
Involved Region or Country		North America						
Additional Options (RPO)		UVC						
Condition		A Dealer or Upfitter may be looking for information on installing the factory provided rearview camera (RPO UVC.)						
		Note: Camera, Extension Harness, and Mounting Bracket are shipped with the vehicle from the assembly plant.						
Cause		Information not readily available in Service Information (SI.)						

### Correction:

Reference the latest version of GM Upfitter Integration Bulletin 150. The information can be found at http://www.gmupfitter.com/ under the "Technical Bulletin" Tab and then "Show all bulletins."

### Version History

2		
05/17/2019 - Created on.		
05/26/2020 - Update to add 2020 Model Year		
05/25/2021 - Update to add 2021 Model Year		
	05/26/2020 - Update to add 2020 Model Year	



GENERAL MOTORS

© 2021 General Motors. All Rights Reserved.