

Field campaign

Topic	Rear brake pad - Shim installation (SC 20/32)
Market area	United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2061344/4
Campaign number	EB74
Note	
Type	
US code	

Vehicle data

Bentayga

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2021	E	*	*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
SJA	*	*	*	M	C	033545	037797		

Documents

Document name
master.xml
sc2032vinlist.pdf

Notes

- Repair instructions

Technical background

Fitment of shims to the rear brake pads, specific grease should also be applied to the shims

Remedy

In high ambient temperatures in conjunction with low speed, low pressure brake vibration is damped by the fitment of shims and grease

Customer notification

Customers do not need to be informed directly of this campaign. Please ensure that all affected vehicles are checked and repaired during the PDI procedure

Warranty accounting instructions

Time to install shim set

Warranty Type 790

Damage Service Number EB74

Damage Code 0066

Labour

Labouroperation code 46384250

Time 20 TU

Criteria ID 01

Time to remove and refit rear brake pads

Labouroperation code 46382050

Time 50 TU

Time to remove and refit rear wheels

Labouroperation code 44052000

Time 10 TU

Genuine parts

Part number	Description	Quantity
36A 698 219	Shim set for rear brake pads (1 set includes x4 shims – 1 for each pad)	1 set
G 052 560 A2	Vary Bond grease	1 = 1 x 100 gram

IMPORTANT: 1 tube of vary bond grease can be used on multiple vehicles (approximately x1 tube can be used on up to a maximum of 20 vehicles)

Do Not order more grease in the event that you already have stock

Parts supply

When applicable the required replacement parts should be ordered from Bentley Motors Limited Crewe or through your regional Bentley parts distribution centre

Parts despatch control

Please raise a PCMS quoting Service Campaign EB74 to ensure the parts are released

NOTE: A DISS query is not required when ordering parts for this Service Campaign

Repair instructions

- Notes

Technical background

Fitment of shims to the rear brake pads, specific grease should also be applied to the shims

Check

If the vehicle is not already listed as repaired in the "Repair History" (Elsa Pro), check for the yellow paint completion mark (see Identification section), should neither be evident continue with the procedure detailed in the "Work" section of this procedure.

Control

All applicable VIN's require the procedure to be conducted during the PDI procedure

Genuine parts

Part number	Description	Quantity
36A 698 219	Shim set for rear brake pads	1 set (1 set includes x4 shims – 1 for each pad)
G 052 560 A2	Vary Bond grease	1 = 1 x 100 gram

IMPORTANT: 1 tube of vary bond grease can be used on multiple vehicles (approximately x1 tube can be used on up to a maximum of 20 vehicles)

Do Not order more grease in the event that you already have stock

Work

VERY IMPORTANT: The application of the grease MUST be exactly as shown/detailed, Ensuring the exact amount of grease is applied to the locations shown

NOTE: *Warranty payments for repeat repairs will not be considered if the grease is deemed to have not been applied correctly*

1. Remove the rear brake pads as per Repair manual Rep.Gr 46 - Rear Brake Pads - To Remove and Fit and check the actual condition of the brake pads – NOTE: Make note of the position of the rear pads for installation purposes.

CAUTION: The performance of the car will be affected if the brake pads are installed in the incorrect position

2. Carefully clean the back plate of the pad using a suitable brake cleaner **IMPORTANT:** Take care not to damage the rubber on the bonded shim

3. Install one shim from the shim kit 36A 698 219 to each rear brake pad, ensuring that when fitted the new shim is seated flat against the brake pad bonded shim

4. Referring to Figure 1 - Apply 6 dots of grease (<1.0g in total) to the inside face of the clip on shim



Figure 1

- Referring to Figure 2 – Using a suitable spatula spread the grease to an even layer condition



Figure 2

- Assemble the clip-on shim onto the pad - Squeeze together firmly to remove any excess grease which comes out from between the new shim and the brake pad bonded shim NOTE: Ensure the new shim is seated flat against the brake pad bonded shim
5. Referring to Figures 3 and 4 - Clean the pad abutments & the spring clips, then apply a small dot of grease to them



Figure 3



Figure 4

- Clean the pad abutment faces on the calliper carrier – scrape off any dirt and brake dust which has accumulated, then use a suitable brake cleaner
- Wipe the face of the piston to remove any brake dust or dirt
- Refit the rear brake pads as per Repair manual Rep.Gr 46 - Rear Brake Pads - To Remove and Fit, taking care not to dis-lodge the grease/shims before the pads are in position.

6. Road test the vehicle as part of the PDI road test procedure

- On return from road test, visually check for any excess grease which may have come out from between the two shims and remove with suitable cleaner

7. On completion place a yellow paint completion mark on the brake fluid reservoir – Refer to the Identification section

Identification



▪ Repair instructions ▪ Notes

SJAAM2ZV6MC033545	SJAAM2ZV8MC033904	SJAAM2ZV1MC037423
SJAAM2ZV9MC033572	SJAAM2ZVXMC033905	SJAAR4ZV7MC037424
SJAAM2ZV5MC033648	SJAAM2ZV3MC033907	SJAAM2ZV9MC037427
SJAAM2ZV5MC033651	SJAAM2ZV5MC033908	SJAAM2ZV4MC037433
SJAAM2ZV7MC033652	SJAAM2ZV7MC033909	SJAAM2ZV1MC037440
SJAAM2ZV4MC033687	SJAAM2ZV3MC033910	SJAAM2ZV5MC037442
SJAAM2ZV6MC033691	SJAAM2ZV5MC033911	SJAAM2ZV4MC037447
SJAAM2ZV8MC033692	SJAAM2ZV0MC033914	SJAAM2ZV9MC037458
SJAAM2ZV6MC033710	SJAAM2ZV6MC033917	SJAAM2ZV0MC037459
SJAAM2ZV0MC033721	SJAAM2ZV2MC033929	SJAAM2ZVXMC037467
SJAAM2ZV3MC033731	SJAAM2ZV4MC033933	SJAAM2ZV1MC037471
SJAAM2ZV4MC033737	SJAAM2ZV3MC033941	SJAAR2ZVXMC037485
SJAAM2ZV6MC033738	SJAAM2ZV8MC033949	SJAAM2ZV5MC037487
SJAAM2ZV6MC033741	SJAAM2ZV8MC033952	SJAAM2ZV0MC037493
SJAAM2ZV5MC033746	SJAAM2ZV7MC033957	SJAAM2ZV8MC037502
SJAAM2ZV9MC033748	SJAAM2ZV9MC033961	SJAAM2ZV7MC037510
SJAAM2ZV2MC033753	SJAAM2ZV1MC033968	SJAAM2ZV9MC037511
SJAAM2ZVXMC033757	SJAAM2ZV7MC033974	SJAAM2ZVXMC037520
SJAAM2ZVXMC033760	SJAAM2ZV4MC033981	SJAAM2ZV5MC037523
SJAAM2ZV5MC033763	SJAAM2ZV5MC033987	SJAAR2ZV0MC037527
SJAAM2ZV4MC033771	SJAAM2ZV9MC033989	SJAAM2ZV2MC037530
SJAAM2ZVXMC033774	SJAAM2ZV9MC033992	SJAAM2ZV5MC037554
SJAAM2ZV5MC033777	SJAAM2ZV4MC033995	SJAAM2ZV4MC037559
SJAAM2ZV7MC033781	SJAAM2ZV2MC034000	SJAAM2ZV6MC037563
SJAAM2ZV3MC033793	SJAAM2ZV8MC034003	SJAAM2ZV8MC037578
SJAAM2ZV9MC033796	SJAAM2ZV5MC034010	SJAAM2ZV5MC037585
SJAAM2ZV2MC033798	SJAAM2ZV9MC034012	SJAAR2ZV2MC037593
SJAAM2ZV4MC033804	SJAAM2ZV8MC034017	SJAAR2ZV1MC037598
SJAAM2ZV1MC033825	SJAAM2ZV1MC034019	SJAAM2ZV1MC037602
SJAAM2ZV3MC033826	SJAAM2ZVXMC034021	SJAAM2ZV5MC037621
SJAAM2ZV7MC033828	SJAAM2ZV3MC034023	SJAAR2ZV5MC037636
SJAAM2ZV2MC033834	SJAAM2ZV0MC034027	SJAAM2ZVXMC037646
SJAAM2ZV1MC033839	SJAAM2ZV3MC034037	SJAAM2ZV6MC037658
SJAAM2ZV8MC033840	SJAAM2ZV2MC034045	SJAAR2ZV7MC037668
SJAAM2ZV1MC033842	SJAAM2ZV6MC034047	SJAAM2ZV0MC037669
SJAAM2ZV3MC033843	SJAAM2ZV8MC034051	SJAAM2ZV4MC037674
SJAAM2ZV0MC033847	SJAAM2ZV7MC034056	SJAAM2ZV8MC037676
SJAAM2ZV2MC033848	SJAAM2ZV9MC034057	SJAAM2ZV1MC037681
SJAAM2ZV0MC033850	SJAAM2ZV7MC034171	SJAAR2ZV3MC037683
SJAAM2ZV4MC033852	SJAAM2ZVXMC034245	SJAAM2ZV9MC037704
SJAAM2ZV8MC033854	SJAAM2ZV9MC034267	SJAAM2ZV8MC037712
SJAAM2ZVXMC033855	SJAAM2ZV4MC037190	SJAAR2ZV5MC037717
SJAAM2ZV1MC033856	SJAAM2ZV9MC037217	SJAAM2ZV6MC037725
SJAAM2ZV3MC033857	SJAAM2ZV3MC037259	SJAAR2ZV1MC037729
SJAAM2ZV3MC033860	SJAAM2ZV2MC037267	SJAAM2ZV0MC037736
SJAAM2ZV5MC033875	SJAAM2ZV2MC037320	SJAAM2ZV2MC037737
SJAAM2ZV7MC033876	SJAAM2ZV6MC037322	SJAAM2ZV4MC037738
SJAAM2ZV0MC033878	SJAAM2ZV9MC037329	SJAAM2ZVXMC037758
SJAAM2ZV2MC033879	SJAAM2ZV8MC037354	SJAAM2ZV1MC037759
SJAAM2ZV0MC033881	SJAAM2ZVXMC037355	SJAAM2ZV3MC037763
SJAAM2ZVXMC033886	SJAAM2ZV6MC037370	SJAAR2ZV0MC037768
SJAAL14VXMC033889	SJAAM2ZV8MC037371	SJAAM4ZV1MC037773
SJAAM2ZV5MC033892	SJAAR2ZV5MC037376	SJAAM2ZV5MC037778
SJAAM2ZV9MC033894	SJAAM2ZV2MC037379	SJAAR2ZV4MC037790
SJAAM2ZV2MC033896	SJAAM2ZV0MC037381	SJAAR2ZV1MC037794
SJAAM2ZV4MC033897	SJAAM2ZV3MC037391	SJAAM2ZV7MC037796
SJAAM2ZV6MC033898	SJAAM2ZV6MC037403	SJAAR2ZV7MC037797
SJAAM2ZV8MC033899	SJAAR4ZV1MC037404	
SJAAM2ZV4MC033902	SJAAM2ZV5MC037408	