21PBF - Daytime Running Lamp Functionality - TC: 2021287

6/16/2021

Number	
21PBF	
Supplier	
Peterbilt	
Description	
21PBF - Daytime Running Lamp Functionality - TC: 2021287	
Date	
6/14/2021	
What's New	

Safety Recall – Interim Notification - The Daytime Running Lamps (DRLs) may turn off while the vehicle is in motion and the headlamps, fog lamps or turn signals are not on. This is non-compliant with Canadian Regulation CMVSS 108, which states that the DRLs must be on while the vehicle is in motion without certain other lamps being activated. This bulletin will be updated when a repair is available.

Introduction

Peterbilt has determined that a non-compliance, which relates to motor vehicle safety, exists in certain model 579, 567, 536 and 389 vehicles manufactured between 03/20/2018 and 05/14/2021. This is non-compliant with Canadian Regulation CMVSS 108, which states that the DRLs must be on while the vehicle is in motion without certain other lamps being activated.

Resolution

This bulletin will be updated when a repair is available.

Authored by: PR