

# TECHNICAL TOPICS

## ELECTRICAL



Wireless Device Charger Module (WDCM) Not Charging iPhone 12	2019 – 2021 Defender, Discovery, Discovery Sport, Evoque, Velar, E-Pace, F-Pace, I-Pace, XE, XF, with wireless charger
<u>Customer Voice:</u> – Customer States iPhone 12 with MagSafe not charging when using the Wireless Device Charger feature	 A photograph showing the interior of a vehicle's center console. A smartphone is placed on a wireless charging pad, which is integrated into the dashboard. The dashboard features a digital display showing the temperature as 19.5 degrees Celsius. The center console also includes a gear selector and various control buttons.
<u>Technical Description:</u> – Wireless Device Charger Module doesn't support the new iPhone 12 MagSafe feature	<u>Status:</u> – If the WDCM is at AA or AB level, please replace the WDCM hardware following TOPIX section 415-01 – If the WDCM is at AC level, please update the WDCM software using Pathfinder <b>SSM75426 Jaguar, SSM75427 Land Rover have been released for this concern.</b>



PRINTED COPIES ARE UNCONTROLLED