

Update to DiagnosticLink 8_14SP3 Release

Communication Type: Service Programs

Date: 9/3/2021

As communicated previously an issue discovered in DiagnosticLink version 8.14SP1 was fixed with the release of 8.14SP3 on August 26th. The issue related to incorrect parameter data being sent to the server for some Chassis ECUs.

Records indicate a population of users who are still using older versions of the tool.

While server mitigation efforts were put in place, if your location has not already, please update all instances of DiagnosticLink to 8.14SP3.

Service Diagnostics and Tools