

WML0 Stop Delivery – Retrofitting loudspeaker booster

Version 1

WML0 Stop Delivery – Retrofitting loudspeaker booster

Vehicle blocking

Vehicles must not be delivered to customers until the required remedial measure has been carried out. Therefore, please carry out following Stop Delivery, immediately.

Important Information:

- A VIN list is attached to this post and will be updated weekly
- At present, no statement can be made about the availability of parts. Together with our suppliers, we are working at high priority to procure the required capacities of components. As soon as these are available, we will inform you immediately. In the meantime, please refrain from requests regarding the availability of parts.
- The Technical Information will be published at a later date.

- The creation of PCSS jobs as well as the invoicing of the campaign is only possible with the availability of the remedial measure.

Overview

Due to worldwide semiconductor shortages experienced by some suppliers, the affected vehicles were built without a loudspeaker booster.

As a result, audio output is not available on these vehicles.

For this reason, the loudspeaker booster must be retrofitted on the affected vehicles before handing the vehicles over to customers once the control unit is available.

Model type	<ul style="list-style-type: none"> • Macan (95B) • Cayenne (9YA/9YB)
Model year	2022
Vehicle specifications	BOSE Surround Sound System (M-No. 9VL)
Number of affected vehicles	TBD*

*Please note due to newly produced vehicles from current production, more vehicles will be assigned to this campaign until loudspeaker boosters are available.

Vehicle usage

The vehicles may only be driven for loading and unloading purposes in the transport chain and, if necessary, by dealer personnel only.

A further use is not permitted. Test drives are to be omitted.

Test instructions and remedial measures

Will be communicated once available.

[VIN_List_Report_WML0_2021-09-28.xlsx](#) ⓘ

8.2 KB

(61 views)

Created by [Mitchell Grasser](#) on Sep 28, 2021 4:59 PM. Last modified by [Mitchell Grasser](#) on Sep 29, 2021 6:34 PM.

566 Views

Categories: Workshop Campaigns, Cayenne, Macan, Stop Sale

Tags : [95b](#), [my m](#), [9ya 9yb](#), [wml0](#)

Content and Topics

Personal

Manage

Create

- Your Groups >
- Your Content >
- Your Places >
- Edit Profile >
- Change Password >
- Admin Console >
- PPN Administration >
- Discussion >
- Files >
- Document >
- Collaboration >
- Document
- Blog Post >
- Poll >
- Event >
- Photo Album >
- Idea >
- Space >
- Group >

© 2021 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. [009](#)