

2021.0 DEFENDER (LE), 415-00

ICCM (INFOTAINMENT COMPUTE CONTROL MODULE) - SOFTWARE

VERSION: IP31 (G2956294)

PIVI IP31

Software Release Date: 2021-11-16

SOFTWARE RELEASE NOTES

NOTE

THE SOFTWARE UPDATE FOR THIS RELEASE NOTE IS AVAILABLE ON THE FOLLOWING SYSTEMS -

- Software Over The Air (SOTA)
- Pathfinder

INTRODUCTION

This Document contains the following information:

New features included in this release

- [Phone App](#)
- [Radio](#)
- [Speech](#)

Issues fixed in this release

- [Audio](#)
 - [Connectivity](#)
 - [Instrument Panel Cluster Control Module \(IPC\)](#)
 - [Navigation](#)
 - [Personalisation](#)
 - [Software Over The Air \(SOTA\)](#)
 - [Speech](#)
 - [System](#)
 - [Telematics](#)
 - [Tow bar](#)
-

NEW FEATURES INCLUDED IN THIS RELEASE

PHONE APP

- Android Auto and Apple Car Play will now work wirelessly

(NORTH AMERICA ONLY)

RADIO

- Sirius XM is now available in PIVI vehicles

SPEECH

This release includes a significant new native speech feature utilizing the cloud capability of the online pack to introduce:

- Cloud navigation searches
- Online media searches for Deezer and TunesIn
- SMS text message dictation (if enabled on the mobile phone)

ISSUES FIXED IN THIS RELEASE

AUDIO

- No audio output when audio system appears to be on issue is now corrected

CONNECTIVITY

- Improved WiFi and HotSpot Functionality
- WiFi hotspot appears but no data connection is available issue as been fixed

INSTRUMENT PANEL CLUSTER CONTROL MODULE (IPC)

- Fixing of flickering IPC for media information

NAVIGATION

- Navigation improvements for freezes and slow boot ups
- The map view intermittently changing the zoom and switching 2D, 3D layout selection without user input is now corrected
- Japan market Navigation can now be launched from the home screen
- Navigation location tracking freezing during a drive cycle issue is now corrected
- Issue from last software update that locks the map to a default location has been corrected

PERSONALISATION

- Improvement in stability of personalisation features

SOFTWARE OVER THE AIR (SOTA)

- Improved robustness of system performance after a SOTA Update
- Improved robustness of firmware updates after a SOTA Update

SPEECH

- Improved speech recognition

SYSTEM

- Improvement in system stability in terms of System reset
- Improvement in general system stability
- Improvements in acoustic reliability / Audio loss
- Improvements in robustness in data persistency
- Graphical Improvements for placeholder screens and overlapping Text

TELEMATICS

- Improvement in stability of the activation and deactivation of telematics services

TOW BAR

- Improvement in Tow Bar functionality

KNOWN ISSUES IN THIS RELEASE

THERE ARE NO KNOWN ISSUES IN THIS SOFTWARE RELEASE.