




Front Accessory Drive noise, Alternator Belt Wear, Alternator Belt Tensioner Failure - MY 2017 And Newer



> **Internal Content**

There has been a product improvement for the Alternator Belt Tensioner. Part Number 23669029 is an improved Belt Tensioner for Alternator drive system. This product is for 2017 and newer trucks both 13 and 11 Liter Engines.

NOTE: Part Number 23669029 is ONLY for the Alternator Belt Tensioner, it is **NOT** compatible for the Fan Belt Tensioner. If Fan Belt Tensioner is needed, order standard part shown in [impact](#).





Tags

[k01157283](#)

[tensioner](#)

[mack](#)

[volvo](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article