



## Volvo Chassis - Bendix Lane Departure Warning System ( LDWS ) Audible Alarm Does Not Deactivate When The Turn Signal Is Switched On - US16; Model Year ( MY ) 2017



> Internal Content

On a Volvo Chassis - US16 - with the Bendix Lane Departure Warning System ( LDW ) the alarm would not cancel once the turn signals were activated. After diagnosing it was found that the harness connector under the cab floor on the driver side as shown below was not connected.



Tags

[k30364124](#)

[volvo](#)

Live UI

## Related links and attachments

No links or attachments available



## Feedback

[Give feedback](#)

to help improve the content of this article