

# 13-059 Optional Parking Brake Released Warning

2/23/2022

 [Edit](#)

 [Clone](#)

---

13-059

## Section

---

Brakes - 13

## Subject

---

Optional Parking Brake Released Warning

## Whats New Abstract

---

**Information Only** – On certain Model Year 2023 chassis with manual transmissions, the optional “audible alarm when door is open and park brake is not set” feature operates incorrectly due to a software issue. Software will be corrected when available.

## Condition

---

Optional “audible alarm with park brake released and door open” operates incorrectly.

## Chassis Affected

---

Certain model 220, 365, 367, 389, 520, 535, 536, 537, 548, 567, 579, and New Model 579 chassis built from 01/10/2022 through 02/27/2022, equipped with Manual Transmissions and optional “Audible Alarm when Door is Open and Park Brake is Not Set.”

## Action

### Information Only

Inform the customer that PACCAR is aware of this issue and is working on a solution. This bulletin will be updated to a campaign and customer letters will be sent out when a solution is available.

## Warranty

### INFO ONLY - No Warranty Claim Info Required

## Parts

---

No Parts Required

## Background

---

A programming error in the VECU software causes the VECU to misread the clutch pedal switch position. This causes the “audible alarm when parking brake released and door open” to operate incorrectly . Software will be corrected when an update is available.

## Procedure

---

Info Only - No Procedure