

SSM 50566 - Various Vehicles - A/C Leak Detection Diagnostics Updated

Some 2022 Ford and Lincoln vehicles may need to perform A/C leak detection diagnostics. The 2022 Workshop Manual (WSM), Section 412-00 for A/C leak detection diagnosis is incomplete and is in the process of being updated. At this time, Pinpoint Test AN of Section 412-00 in the 2022 F-150 WSM can be used temporarily for the service procedure and specifications. Use the correct vehicle specific removal and replacement sections as needed. A new labor operation 19700A45 has also been released to align with the new procedure.

APPLICABLE VEHICLES

2022 CAR: TV U611N AVIATOR
2022 TRUCK: G1 U725N BRONCO
2022 CAR: HD CX430N C-SUV
2022 CAR: TF CX483N CORSAIR
2022 CAR: DQ CD539N EDGE
2022 CAR: TC CX482N ESCAPE
2022 TRUCK: E4 ECONOLINE
2022 TRUCK: B8 U553N EXPEDITION
2022 CAR: TW U625N EXPLORER
2022 TRUCK: BC H567N MEDIUM TRUCK
2022 CAR: GX S922N GT
2022 TRUCK: FE P558N SUPER DUTY
2022 CAR: FE P758N C-PICKUP
2022 CAR: D9 U540N MKX
2022 CAR: ZG S550N MUSTANG
2022 CAR: GW CX727N C-EV
2022 TRUCK: B9 U554N NAVIGATOR
2022 TRUCK: FG P375N RANGER
2022 TRUCK: TH V363N TRANSIT
2022 CAR: HC V408E TRANSIT CONNECT
2022 CAR: HC V408E TRANSIT CONNECT