

Mack Chassis - Diagnostic Trouble Code (DTC) P20CF, Diagnosis And Repair - US14+OBD15 **Emissions, Common Model Year 2016**



> Internal Content

Software improvements have been released to address this DTC.



Tags mack

p20cf fsb 284-064

Related links and attachments

KC-201 FSB 284-064



Feedback

Give feedback

to help improve the content of this article