

IDO - 510 - PRODUCT SUBSTITUTION NOTICE - 2-QUART HYDRAULIC POWER UNIT RESERVOIRS

LEVELNG & STABILIZATION

THIS DOCUMENT IS FOR INTERNAL USE ONLY! DO NOT DISTRIBUTE

The attached letter has been sent by Lippert Components, Inc. to all affected OEMs. This document is for internal informational purposes only and is not to be distributed in any manner.



March 1, 2022

Product Substitution Notice - 2 -quart hydraulic power unit reservoirs

Dear Valued Customer:

Please be advised, due to material shortages, Lippert intends to use substitute reservoirs per application requirements. Power unit bases (pump/motor) will be retrofitted with the appropriate-size reservoir and corresponding pick up tubes.

There is no effect on installation or operation for the customer with the substitute reservoir. There is no change in part number or in price. Test reports are available upon request. The change is expected to begin immediately and continue as inventory dictates.



If you have any questions, please feel free to call me directly or your LCI representative. We value and appreciate your business and partnership.

Sincerely,

Mason Ogle

VP of RV Sales Lippert Components, Inc. c: 574.849.1742 mogle@lci1.com

Frequently Asked Questions:

- 1. Will a new part number be required? No, there is no part number change.
- **2. Does the price change for the item?** No, there is no price change.
- **3. Is the new part wholly interchangeable with the previous version of the part?** Yes, the power units are interchangeable.
- **4. Does the customer need to replace inventory?** No, the change will be made on a running basis starting immediately and continue as inventory dictates.