



Warranty Policies and Procedures Bulletin

Audi Warranty

Number: AWA 22-04

Subject: Takata Airbag Inflator Limited Warranty Extension

Date: Apr 25, 2022

Dealers: U.S., Puerto Rico

This document modifies the Audi Warranty Policies and Procedures Manual.

Effective: April 25, 2022

Takata Airbag Inflator Limited Warranty Extension is applicable for certain Audi vehicles:

- MY 2006-2013 Audi A3
- MY 2005-2008 Audi A4 Avant, Audi A4 Sedan, Audi S4 Sedan, Audi S4 Avant
- MY 2007-2009 Audi A4 Cabriolet, Audi S4 Cabriolet
- MY 2010-2012 Audi A5 Cabriolet, Audi S5 Cabriolet
- MY 2006-2011 Audi A6 Avant
- MY 2005-2011 Audi A6 Sedans
- MY 2009-2012 Audi Q5
- MY 2017 Audi R8 Coupe and Audi R8 Spyder
- MY 2008 Audi RS4 Cabriolet
- MY 2007-2008 Audi RS4 Sedan
- MY 2007-2011 Audi S6 Sedan
- MY 2016-2017 Audi TT Coupe, Audi TT Roadster

Takata Airbag Inflator Limited Warranty Extension

For vehicles applicable to the Takata Airbag Inflator Recall, Audi has extended the Warranty coverage for the Driver and Passenger Takata Airbag Inflator under the following parameters:

Default Coverage	Once Default Coverage Expires:	
	Recall completed on or before 11/10/2021	Recall completed after 11/10/2021
10 years from the date the recall was completed or 150,000 miles from the vehicles original in-service date (whichever occurs first)	Through 11/10/2023 or 75,000 miles from date of recall completed (whichever is greater)*	2 years from the date the recall was completed or 75,000 miles from date of recall completed (whichever is greater)*
Elsa Contract Type Takata-10Y/150K	Elsa Contract Type Takata-2Y & Takata-75K	

*once default coverage has expired, the vehicle only needs to meet the time OR mileage (whichever is greater to apply).

The vehicle’s original in-service date is defined as the date the vehicle was delivered to either the original purchaser or the original lessee; or if the vehicle was first placed in service as a “demonstrator” or “company” car, on the date such vehicle was first placed in service.



Warranty Policies and Procedures Bulletin

What is Covered

During the time/mileage period specified above, an authorized Audi Dealer will diagnose and replace the Driver and/or Passenger Takata Airbag Inflator at no cost to the customer if diagnosis confirms that the Driver and/or Passenger Takata Airbag Inflator has failed from a warranty defect.

If diagnosis reveals that the vehicle has an unrelated issue(s), diagnosis and any necessary repairs to correct such issue(s) will not be covered under this warranty extension.

Transferability

This warranty extension is fully transferable to subsequent owners.

Additional information

This warranty extension does not cover damage or malfunctions caused by outside influence, such as an accident, or vehicle misuse or neglect, nor does it cover repairs that are necessary for proper diagnosis of these conditions or that are required to bring the vehicle up to factory specifications.

Inoperable vehicles, vehicles with the totaled status, salvaged, rebuilt or flood damage title are excluded from coverage under this Warranty Extension.

Vehicle Eligibility

To determine if a vehicle is eligible for the Takata Airbag Inflator Limited Warranty Extension, check the VIN in Elsa > Vehicle Data. If the warranty extension is applicable to the vehicle, the "Enhanced Coverage" section of the "Vehicle Data" screen in Elsa will be populated with the warranty extension parameters.

The "Warranty" section of the "Vehicle Data" screen will also show Warranty Key "U52" indicating this vehicle is eligible for this Warranty Extension.

Claim Processing

For the Takata Limited Warranty Extension:

Claim Type: 110

Service Number: 6955

Warranty Key: U52

Questions or concerns may be directed to Audi Warranty at 866.677.2834 or AudiWarranty@audi.com.

Information in this bulletin is Warranty policy. All warranty claims must be submitted in accordance with the most recent edition of the Audi Warranty Policies and Procedures Manual. Claims are subject to review and/or audit by Audi Warranty.