Polestar

Technical Journal

TITLE: SiriusXM Song/Artist Information does not Update on Screen									
REF NO:	ISSUING DEPARTMENT:	CAR MARKET:							
TJ 36141.1.1	Technical Service	United States and Canada							
	PARTNER:	ISSUE DATE:	STATUS DATE:						
	3 US 7515	2021-12-14	2022-04-01						
FUNC GROUP: 3900	FUNC DESC: Media, navigation and communication	Page	1 of 1						

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

*New repair information under Service

When listening to SiriusXM radio, the customer may experience the song/artist information not updating on the center screen when changing channels or when the song changes.

CSC Customer Symptom Codes

Code	Description
XD	Audio other/Audio unit display does not work
2P	Satellite radio/Does not work

DTC Diagnostic Trouble Codes

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
534							2021-2022		-	202037-999952

SERVICE:

* This concern is resolved with the latest IHU software (released 3/28/2022). To install it, download a Total Upgrade

VEHICLE REPORT:

Not required