

July 18, 2022

Product Change Notice - Standardized strut bracket size for baggage doors


Dear Valued Customer:

Please be advised we plan to switch the strut brackets for our baggage doors to a standard size. Currently a larger-size strut bracket is installed on the outside of the baggage door. The smaller strut utilized on the inside of the door will become the standard for both inside and out.

The part numbers for the larger bracket are 146368 and 309688. The part number for the new, standard bracket is 333476.

There is no change in fit, function, installation or operation for the customer. There is also no price change. The change is being made to streamline the door production process by eliminating multiple part numbers.

The change will take place on a running basis starting in mid-September.



If you have any questions, please feel free to call me directly or your LCI representative. We value and appreciate your business and partnership.

Sincerely,

Scott McKinnon
Product Manager
c: 269.832.6800
smckinnon@lci1.com

Frequently Asked Questions:

- 1. Will a new part number be required?** Yes, the part numbers for the larger bracket are 146368 and 309688. The part number for the new, standard bracket is 333476.
- 2. Does the price change for the item?** No, there is no price change.
- 3. Is the new part wholly interchangeable with the previous version of the part?** Yes, the doors are interchangeable with either bracket.
- 4. Does the customer need to replace inventory?** No, the change will be made on a running basis, starting mid-September.