

# CAMPAIGN LAUNCH STATUS

## N707 UPS - LAMP ANIMATION ON UNLOCKING/LOCKING



UPDATE PRIOR TO SALE N707- LAMP ANIMATION ON UNLOCKING/LOCKING – CCF UPDATE	
AFFECTED MODELS	2023 New Range Rover
VOLUME AFFECTED	Current Volume: USA 293 Canada 17
REPAIR	When the vehicle is locked/unlocked the position lamps illuminate but do not animate as expected. Retailers will perform a Car Configuration File(CCF) update to enable the feature.
REPAIR TIME	0.2 hrs + DIDO
CAMPAIGN LAUNCH	June 27 <sup>th</sup> , 2022
Notes	All affected vehicles in retailer stock must have this repair completed prior to sale and delivery.

