

DIAGNOSTIC TOOL 2022-07



Notice Information

Ref	21767
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (USCA) – June 21, 2022

TOL Ref. #21767-SVC

DIAGNOSTIC TOOL 2022-07

Triumph has released diagnostic software [version 2022-07](#). It is now available to download and update your workshop computer. Please download (from the Triumph Diagnostic Tool page under the Service/Technical menu on TOL) today and commence using immediately.

This release addresses the following subjects with more information and model listing in the attached Release Notes.

- New Software Functionality and Improvements
- New Chassis ECM Calibrations
- New Instrument Calibrations
- Keyless ECM Calibrations
- Suspension ECM Calibrations
- Headlight ECM Calibrations
- Calibration Description Corrections
- Bug Fixes

Reminder:

- Please ensure all new bikes have the latest software download at PDI
- Please ensure the latest software is download on all bikes being serviced
- **PLEASE ENSURE ALL RELEVANT STAFF ARE INFORMED OF THIS UPDATE**

The attached [TDT Release Notes 2022-07](#) are stored and available to download anytime from the dedicated TDT page within TOL.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.