

DIAGNOSTIC TOOL 2022-08.1



Notice Information

Ref	22036
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Parts / Accessories Coordinator, Sales Executive, Clothing Sales, Sales Manager, Aftersales Manager, Service Leader / Advisor, Accounts / Admin, Marketing Executive
Subject:	Service/Technical

TOL NOTICE (USCA) – July 22, 2022

TOL Ref. #22036-SVC

DIAGNOSTIC TOOL 2022-08.1

Triumph has released diagnostic software [version 2022-08.1](#). It is now available to download and update your workshop computer. Please download (from the Triumph Diagnostic Tool page under the Service/Technical menu on TOL) today and commence using immediately.

This release addresses the following subjects with more information and model listing in the attached Release Notes.

Engine ECM Calibrations

There was an issue with the latest version of the Triumph Diagnostic Tool (TDT) version **2022-08** that was preventing access to instrument diagnostics on some LCD instrument packs. This may have prevented dealers from being able to reset the service interval.

Updated calibrations released for the following models:

- Tiger 1200 GT
- Tiger 1200 GT Pro
- Tiger 1200 GT Explorer
- Tiger 1200 Rally Pro
- Tiger 1200 Rally Explorer.

Instrument Calibrations

Updated calibrations released for the following models: [SEE NOTES]

- Trident 660
- Tiger Sport 660
- Tiger 900 Bond Edition
- Tiger 1200 XCX
- Tiger 1200 XRX
- Tiger 1200 XRX – LRH.

Connectivity Module Calibrations

New calibration released for all models that can be equipped with a Triumph Connectivity Module. [SEE NOTES]

Known Issues in this Release

The DTCs listed below may not clear when the Erase DTCs button is clicked. These DTCs can be ignored until further notice:

- U1508
- C1313

Reminder:

- Please ensure all new bikes have the latest software download at PDI
- Please ensure the latest software is download on all bikes being serviced
- **PLEASE ENSURE ALL RELEVANT STAFF ARE INFORMED OF THIS UPDATE**

The attached **TDT Release Notes 2022-08.1** are stored and available to download anytime from the dedicated TDT page within TOL.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.