



# Service Bulletin

Bulletin No.: 17-NA-331

Date: March, 2023

## INFORMATION

**Subject:** Rear View Camera Guidelines Not Present at Times

**Attention:** This bulletin **ONLY** applies to the year, model and RPO combinations shown in the table below if also equipped with Single Rear Vision Camera System or (RPOs UVC, UVB).

Year	Make and Model	BYOM2 (RPOs IOA, IOB)	Info 3.0 (RPOs IOR, IOS, IOT, IOU)	NGI (RPOs IO5, IO6)
2017	Cadillac Escalade Models			X
2017	Chevrolet Silverado	X		X
2017	Chevrolet Suburban			X
2017	Chevrolet Tahoe			X
2017	GMC Sierra	X		X
2017	GMC Yukon Models			X
2018	Buick Enclave			X
2018	Buick LaCrosse			X
2018-2019	Buick Regal		X	
2018	Cadillac ATS		X	
2018	Cadillac Escalade Models			X
2018	Cadillac CT6			X
2018-2019	Cadillac CTS		X	
2018	Cadillac XT5			X
2018	Cadillac XTS		X	
2018-2021	Chevrolet Bolt EV	X		
2018	Chevrolet Camaro	X		X
2018	Chevrolet Colorado	X		X
2018	Chevrolet Corvette			X
2018	Chevrolet Cruze	X		X
2018	Chevrolet Equinox			X
2018	Chevrolet Impala			X
2018	Chevrolet Malibu	X		X
2018	Chevrolet Silverado	X		X
2018	Chevrolet Sonic		X	
2018	Chevrolet Suburban			X
2018	Chevrolet Tahoe			X
2018	Chevrolet Traverse	X		X
2018	Chevrolet Trax		X	
2018	Chevrolet Volt			X
2018	GMC Acadia	X		X
2018	GMC Canyon	X		X
2018	GMC Sierra	X		X

Year	Make and Model	BYOM2 (RPOs IOA, IOB)	Info 3.0 (RPOs IOR, IOS, IOT, IOU)	NGI (RPOs IO5, IO6)
2018	GMC Terrain		X	
2018	GMC Yukon Models			X

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:	
		from	to	from	to			
Buick	Enclave	2018						
	LaCrosse							
	Regal							
Cadillac	ATS	2018						
	CT6							
	CTS							
	Escalade Models	2017	2018					
	XT5							
	XTS							
Chevrolet	Bolt EV	2018				—	—	
	Camaro							
	Colorado							
	Corvette							
	Cruze							
	Equinox							
	Impala							
	Malibu							
	Silverado							2017
	Sonic							2018
	Suburban							2017
	Tahoe							2018
	Traverse							
Trax								
Volt								
GMC	Acadia	2017						
	Canyon							
	Sierra							
	Terrain							
	Yukon Models							

<b>Involved Region or Country</b>	North America, Europe, Uzbekistan, Middle East, Israel, Brazil, Chile, Colombia, Ecuador, Guatemala, Peru, Japan, Cadillac Korea (South Korea), GM Korea Company, China, Thailand, Malaysia, Vietnam, Egypt, South Africa
<b>Additional Options (RPOs)</b>	<b>Important:</b> This bulletin <b>DOES NOT</b> apply to vehicles with (RPOs UVH, UVJ). Equipped with VISION-REAR VIEW, MONO, ANALOG or VISION-REAR VIEW, MONO, HD DIGITAL (RPOs UVC, UVB) and any of the model/RPO combinations in the table above.
<b>Condition</b>	Some customers may comment that the rear view camera (RVC) guidelines are temporarily not available at times but the RVC will remain on during the concern. Additionally, no related DTCs will be found if this bulletin applies. One example of when this concern may be observed is if a customer quickly starts the car and immediately places the shifter in Reverse while the infotainment system is still in the initial boot up process.
<b>Cause</b>	This is a result of the RVC image being provided via an alternate robust RVC feed from the Video Bypass Module (NGI systems) or from the radio (BYOM2 and Info 3.0 systems). This alternate robust RVC feed is provided in the event that the primary RVC feed is not available for any reason just to ensure that the RVC image is always present when in Reverse.
<b>Correction</b>	If this concern is experienced and no related codes are present, <b>DO NOT</b> replace any parts as it is normal for the RVC guidelines not to be present when the RVC image being displayed is from the alternate robust RVC feed. If this occurs after quickly starting the vehicle and immediately placing the shifter in Drive, the RVC guidelines can be displayed again in most cases if they are really needed by safely coming to a stop, placing the transmission in Park for a moment, and then shifting to Reverse again.

<b>Version</b>	3
<b>Modified</b>	Released October 17, 2017 Revised February 17, 2023 – Added the 2019-2021 Model Years to Bolt EV, RPO UVB and updated the Involved Region or Country section. Revised March 15, 2023 – Added the 2019 CTS and 2018-2019 Regal models.

