Reference Bulletins: QB \$10227

Polestar Automotive USA Inc. on behalf of Polestar Performance AB, have decided to launch Service Action S10227 on certain model year 2021 – 2023 Polestar 2 vehicles.

Polestar investigations have identified that vehicles are unable to receive Over-The-Air (OTA) updates due to old or conflicting software.

To remedy the concerned vehicles, Polestar will perform a software upgrade to enable OTA updates.

A total of 1,162 U.S. and 117 Canadian vehicles are eligible for this service action.

The following part numbers apply:

Part Number	Description	Qty
32292674	Total Upgrade PS2	1