

**On-car analysis list from September 10th, 2014
please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta, Jetta SW, Golf, Beetle, Beetle Conv, Passat	14	2.0TDI CJAA / CKRA	All	EGR valve	Mil-on with fault code P046C, untouched vehicles
Body	Jetta, Passat	14 - 15	All	All	Car -Net Button	Car-Net button fell into the overhead console housing
	Passat	12 - 15	All	All	B-Pillar Trim	Customer states the B-Pillar trim is cracking
	Jetta	14	All	All	Front windows binding during operation causing false pinch protection activation. VIN range EM236581 to EM350000 or EM386721 to EM500000	Front window(s) binding / Windows roll back down once reaching the top of travel
Electrical	Golf, GTI	15	All	All	HID headlamp w/ LED type DRL inoperative ONLY	Customer states the LED daytime running light strip does not light up
	Jetta	14 - 15	All	All	Horn activation on it's own	Customer states the horn beeps on it's own when driving/turning the steering wheel
Chassis	No Current Topics					