

**On-car analysis list from October 16th, 2014  
please contact VW Helpline before attempting repair**

	<b>Models</b>	<b>MY</b>	<b>Engine</b>	<b>Transmission</b>	<b>Topic</b>	<b>Customer Complaint</b>
<b>Powertrain</b>	Jetta, Jetta SW, Golf, Beetle, Beetle Conv, Passat	14	2.0TDI CJAA / CKRA	All	EGR valve	Mil-on with fault code P046C, untouched vehicles
<b>Body</b>	Jetta, Passat	14 - 15	All	All	Car -Net Button	Car-Net button fell into the overhead console housing
<b>Electrical</b>	Golf, GTI	15	All	All	HID headlamp w/ LED type DRL inoperative ONLY	Customer states the LED daytime running light strip does not light up
	Jetta	14 - 15	All	All	Horn activation on it's own	Customer states the horn beeps on it's own when driving/turning the steering wheel
<b>Chassis</b>	All (Excluding Routan)	14	All	All	Wheel Center Cap Loose / Fell Off	Customer or technician notices wheel center caps fell off / are loose or the center cap tabs are cracked/broken. Limited to part number: 3B7601171 XRW