

Subject MIL On DTC P0A2A1F (Drive Motor "A" Temperature Sensor Circuit Intermittent)		Market USA
Service Category Vehicle Interior	Section Meter/Gauge/Display	
Applicability 2021-2023 RAV4 HV		

APPLICABLE VEHICLES

2021-2023

RAV4 HV

CONDITION

2021-2023 RAV4 HV MIL On DTC P0A2A1F (Drive Motor "A" Temperature Sensor Range Intermittent)

RECOMMENDATIONS

This issue is currently under investigation. Please create TAS case and attach a store all health check. Please contact TAS for further instructions. If it is a weekend or a holiday, continue with diagnosis and repair. Please save all parts/ or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references