

Field campaign

Topic	Software update for the rear door control modules - 00BB and 00BC during PDI (SC23/24)
Market area	Australia E04 Bentley rest Asia and Australia (6E04),China 723 Volkswagen (Anhui) Automotive CO (6723),China 796 VW Import Comp. Ltd (Vico), Beijing (6796),Germany E02 Bentley rest Europe (6E02),Japan E03 Bentley Japan (6E03),Korea, (South) E08 Bentley South Korea (6E08),United Arab Emirates E06 Bentley Middle East and Africa (6E06),United Kingdom E01 Bentley UK (6E01),United States E05 Bentley USA and rest America (6E05)
Brand	Bentley
Transaction No.	2071260/2
Campaign number	EC89
Note	
Type	
US code	

Vehicle data

New Continental GT and New Continental GTC

Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
3S3*	2022	E		*	*	*
3S3*	2023	E		*	*	*
3S4*	2022	E		*	*	*
3S4*	2023	E		*	*	*

Chassis numbers

Manufacturer	Filler	Type	Filler	MY	Factory	From	To	Prod from	Prod to
SCB	*	*	*	N	C	096643	098461		
SCB	*	*	*	P	C	004980	012138		

Documents

Document name
master.xml
sc2324vinlistv2.pdf

Notes



Technical background

Software update is available for the left and right hand rear door control modules - Diagnostic address 00BB Driver side and 00BC Passenger side

The software eliminates the rear window short drop function

Remedy

The instructions within the Work section must be conducted as detailed

Customer notification

Please ensure the instructions are conducted during the PDI process

Warranty accounting instructions

Warranty type 790

Damage service number EC89

Damage code 00 66

Criterion ID 01

Time to conduct the Software Version Management (SVM) update - Rear door control modules

Labour operation code 01 51 00 00

Time As per ODIS log Must not exceed 30 TU

Genuine parts

Not applicable

Parts supply

Not applicable

Parts despatch control

Not applicable

Repair instructions



Technical background

Software update is available for the left and right hand rear door control modules - Diagnostic address 00BB Driver side and 00BC Passenger side

The software eliminates the rear window short drop function

Check

If the vehicle is not already listed as repaired in "Repair history" (in Elsa pro), check for the presence of the blue paint completion mark as shown within the Identification section

If neither are evident please conduct the instructions within the Work section to completion

Genuine parts

Not applicable

Work

Software update to the rear door control modules 00BB and 00BC - Short drop function elimination



The following software update eliminates the rear window short drop function

- The closed-circuit voltage of the vehicle must be at least 12.5 V during the update. Connect a suitable battery charger to the vehicle. For further information refer to the Repair manual
- During the update switch off all unnecessary consumers (ventilation, seat heater, interior illumination etc) ensure the main light switch is set to 'off' and leave the driver's door open
- Because of the highest transmission stability you **MUST** use the diagnosis interface VAS 6154 (WiFi diagnostic tool) **ONLY** in USB operation or the cable-connected VAS 5055 for the reprogramming (updating) of control units. If these units are not available, the diagnosis interface VAS 5054 (A) can also be used in USB mode
- Do Not under any circumstances use a Bluetooth connection to conduct the reprogramming (updating) of any control units

1) Referring to Figure 1 - Within the Special functions tab - Select SVM - Code Input (Point A)

• Select Perform test (Point B)




Figure 1

2) Referring to Figure 2 - Enter the SVM code 370WAD01




Figure 2

3) When prompted enter your global user ID and password

- Follow all on screen prompts to continue through the procedure, the identification data will be transferred

4) The control modules will automatically be updated one by one, starting with 00BB (Driver rear) and then 00BC (passenger rear)

5) On completion check the door control module versions against the Reference tables 3 and 4 (depending on Part number/Software version)

[Reference table 3](#)

Door control module	Part number	Software version	Target data container
00BB - Rear driver's door	4M1959955D	0189	V03935413CW
00BC - Rear passenger door	4M1959955D	0189	V03935413CX

[Reference table 4](#)

Door control module	Part number	Software version	Target data container
00BB - Rear driver's door	4M1959955J	0430	V03935405MS
00BC - Rear passenger door	4M1959955J	0430	V03935405MT

6) Switch off the ignition

- Remove the diagnostic interface from the OBD port
- Switch off and remove the battery charger from the vehicle
- Close the bonnet, boot and all doors
- Lock the vehicle
- Wait 5 minutes to allow the vehicle to go into bus silence
- When 5 minutes has elapsed, unlock the vehicle and open the driver's door
- Switch on the ignition

7) **VERY IMPORTANT** - Referring to Rep.Gr 64 - Side glass - To initialise

8) Referring to the Identification section - Apply a blue paint completion mark on the engine partition brace (Figure 3)

Identification

Blue paint completion mark on the engine partition brace



Figure 3

INTERNAL

SCBCF13S4NC096643	SCBDX33S9PC009903	SCBC113S5PC010581	SCBDG4ZG9PC011076	SCBC113S2PC011431
SCBDF33S8NC096919	SCBCG13S5PC009929	SCBCK13S6PC010585	SCBDT4ZGXP011082	SCBDT4ZG6PC011435
SCBDF33S8NC098461	SCBCV13S7PC009937	SCBC113S3PC010594	SCBC113S9PC011085	SCBDT4ZG3PC011439
SCBDK33S4PC004980	SCBCG13S3PC009945	SCBCG13S0PC010602	SCBC113S5PC011097	SCBDX33SXPC011448
SCBDK33SXPC005003	SCBCG13S9PC009951	SCBCK13S7PC010630	SCBCK13SXPC011111	SCBCG13S8PC011450
SCBCT23S7PC005379	SCBDX33S0PC009952	SCBC113SXPC010642	SCBCG2ZG2PC011114	SCBCW13SXPC011453
SCBCT23S8PC005522	SCBCK13S6PC009954	SCBDG4ZG4PC010644	SCBDG4ZG1PC011122	SCBD133S2PC011459
SCBDK33S6PC005743	SCBCG13S1PC009958	SCBCK13S2PC010650	SCBCK13S7PC011129	SCBCT2ZG5PC011460
SCBCX13S0PC006601	SCBCG13S3PC009962	SCBCX13S5PC010658	SCBDG4ZG2PC011131	SCBDT4ZG9PC011462
SCBC113S5PC006983	SCBCK13S4PC009984	SCBC113S4PC010667	SCBC11ZG3PC011134	SCBCT2ZG3PC011473
SCBC113S0PC007118	SCBCK13S8PC009986	SCBCW13S3PC010693	SCBCW13S2PC011141	SCBCJ13S0PC011475
SCBDW33S2PC007333	SCBC11ZG3PC010002	SCBCW13S8PC010706	SCBCT2ZG5PC011149	SCBC113S6PC011478
SCBCG2ZG5PC007428	SCBCX13S2PC010021	SCBC113S1PC010710	SCBC113S3PC011177	SCBDG4ZG9PC011482
SCBCX13S9PC007617	SCBCX13SXPC010025	SCBCG13S4PC010716	SCBCG2ZG9PC011188	SCBCT2ZG5PC011488
SCBDK33S6PC007637	SCBCV1ZG5PC010054	SCBCG2ZG6PC010726	SCBCW13S7PC011202	SCBD133S7PC011490
SCBCX13S8PC007706	SCBCW13S0PC010117	SCBDJ33S3PC010756	SCBCG13S4PC011204	SCBCX13S6PC011494
SCBCG13SXPC007772	SCBDK33S5PC010142	SCBCG13S9PC010758	SCBDG4ZG9PC011210	SCBCW13S1PC011499
SCBCG13S6PC007798	SCBCX13S7PC010144	SCBDG4ZGXP010762	SCBCG2ZG2PC011212	SCBCG13SXPC011501
SCBCG23S2PC007836	SCBCG13S4PC010196	SCBC113S3PC010773	SCBDG4ZGXP011216	SCBCW13S3PC011505
SCBCG13S7PC007924	SCBCK13S1PC010199	SCBCW13S9PC010780	SCBDG4ZG5PC011222	SCBCX13S4PC011509
SCBCX13S1PC007949	SCBCG13S3PC010206	SCBDX33S6PC010782	SCBC113S0PC011234	SCBCG13S2PC011511
SCBDK33S6PC008075	SCBCG13S0PC010213	SCBCW13S2PC010796	SCBDT4ZG7PC011248	SCBDG4ZG5PC011513
SCBCK13SXPC008290	SCBDK33S6PC010215	SCBCK13S3PC010804	SCBCW13S3PC011262	SCBC113S8PC011515
SCBCV13S7PC008352	SCBDT43S3PC010238	SCBCG2ZGXP010812	SCBD133S9PC011264	SCBDG4ZG2PC011517
SCBCK13S6PC008397	SCBCG13S3PC010268	SCBCG13S1PC010818	SCBCW13S0PC011266	SCBC11ZG3PC011523
SCBCT23S7PC008444	SCBCG13S8PC010279	SCBCX13S3PC010822	SCBCG13SXPC011269	SCBCX13S6PC011527
SCBCX13S3PC008519	SCBDT4ZG0PC010281	SCBCG13S4PC010828	SCBCG13S0PC011278	SCBCG13SXPC011529
SCBCG13S3PC008536	SCBDX33S0PC010289	SCBC113S7PC010842	SCBD133S6PC011285	SCBCW13S1PC011535
SCBCX13S0PC008591	SCBDX33S4PC010294	SCBCV1ZG7PC010847	SCBCG13S1PC011287	SCBC113S7PC011537
SCBCG13S4PC008660	SCBDX33SXPC010302	SCBCG2ZGXP010857	SCBCG2ZG6PC011293	SCBCJ13S9PC011555
SCBCG13S9PC008671	SCBCG13S5PC010305	SCBCG13S2PC010861	SCBCW13S9PC011296	SCBDW33S9PC011556
SCBCG13S4PC008738	SCBC113S2PC010313	SCBC113S1PC010884	SCBD133S4PC011298	SCBCX13S6PC011558
SCBCX13S5PC008747	SCBDX33SXPC010316	SCBCG2ZG2PC010903	SCBC113S8PC011305	SCBDW33S4PC011562
SCBCG13S4PC008786	SCBCG13S9PC010324	SCBCW13S1PC010904	SCBCX13S3PC011310	SCBCT2ZG5PC011569
SCBCG13S2PC008835	SCBDT4ZG5PC010342	SCBDX33S2PC010908	SCBCX13S5PC011311	SCBC113S4PC011575
SCBCG13S3PC008911	SCBCG13S2PC010343	SCBCG13S4PC010909	SCBCG13SXPC011319	SCBCT2ZG4PC011577
SCBCG13S1PC009040	SCBCW13S8PC010348	SCBCU13S3PC010991	SCBC113S9PC011328	SCBDT4ZG8PC011579
SCBCG13S8PC009066	SCBDX33SXPC010364	SCBCX13S7PC010919	SCBCW13S5PC011330	SCBCK13S3PC011581
SCBCV13S1PC009139	SCBCG13S1PC010365	SCBCW13S9PC010925	SCBDG4ZG1PC011332	SCBCG13S7PC011584
SCBDX33SXPC009201	SCBCW13S1PC010367	SCBC113S4PC010930	SCBC113S1PC011338	SCBCJ13S9PC011586
SCBDX33S8PC009231	SCBCK13S4PC010374	SCBDG4ZG4PC010935	SCBCW13S8PC011340	SCBDT4ZG4PC011594
SCBCX13S1PC009264	SCBCG13S8PC010380	SCBDX33SXPC010946	SCBD133S5PC011343	SCBCK13S5PC011596
SCBC113S7PC009299	SCBDX33S6PC010393	SCBCJ13S1PC010948	SCBCG13S4PC011347	SCBDX33S7PC011598
SCBDG4ZG9PC009330	SCBDW33S9PC010407	SCBDX33S3PC010951	SCBCG13S7PC011357	SCBDW33S1PC011602
SCBC113S7PC009383	SCBCG13S7PC010421	SCBDG4ZG4PC010952	SCBD133S6PC011366	SCBCJ13S7PC011604
SCBCK13S4PC009418	SCBCK13SXPC010427	SCBCK13SXPC010962	SCBCW13S8PC011368	SCBCG13S6PC011608
SCBDU33SXPC009465	SCBCG13S1PC010429	SCBCJ13S3PC010966	SCBCG2ZG9PC011370	SCBCW13S0PC011610
SCBCX13S8PC009519	SCBCG13S7PC010435	SCBCK13S9PC010984	SCBCT2ZGXP011373	SCBCJ13SXPC011614
SCBDT43S5PC009530	SCBCK13S2PC010437	SCBDJ33S5PC010998	SCBDX33S2PC011377	SCBDT4ZGXP011616
SCBCV1ZG4PC009588	SCBDW33S4PC010461	SCBDT4ZG1PC011004	SCBCG13S6PC011379	SCBDT4ZG1PC011620
SCBCT2ZG5PC009613	SCBCK13S1PC010493	SCBCJ13S9PC011006	SCBCG13S5PC011387	SCBCT2ZG5PC011622
SCBCG13S8PC009620	SCBCX13S0PC010499	SCBCK13S8PC011012	SCBCX13S9PC011389	SCBCK13SXPC011626
SCBCG13S4PC009629	SCBCG13S7PC010502	SCBC113S8PC011014	SCBCG13S2PC011492	SCBCK13S3PC011628
SCBCG13SXPC009702	SCBCK13S2PC010504	SCBCK13S6PC011025	SCBC113S8PC011398	SCBDW33S6PC011630
SCBCG13S7PC009723	SCBCG13S8PC010508	SCBC113S8PC011031	SCBCG13S8PC011402	SCBCG2ZG2PC011632
SCBCT2ZGXP009736	SCBD133S1PC010514	SCBCW13S1PC011034	SCBCW13S7PC011409	SCBDT4ZG1PC011634
SCBCG13S4PC009761	SCBCW13S3PC010516	SCBCK13S0PC011036	SCBCG13S4PC011414	SCBCG2ZGXP011636
SCBCG13S2PC009810	SCBCG13S6PC010541	SCBDW33S0PC011056	SCBDT4ZG6PC011418	SCBCG13S2PC011640
SCBCG13S0PC009837	SCBCK13S7PC010546	SCBCX13S8PC011061	SCBCG13SXPC011420	SCBCT2ZG4PC011644
SCBDX33S9PC009853	SCBCG13S7PC010550	SCBCG2ZG0PC011063	SCBDG4ZG4PC011423	SCBC113S1PC011646
SCBCW13S8PC009880	SCBCG13S0PC010552	SCBC113S5PC011066	SCBCG13S9PC011425	SCBCK13S9PC011648
SCBCG13S9PC009884	SCBCK13S7PC010563	SCBCW13S7PC011068	SCBCG2ZG1PC011427	SCBC11ZG3PC011652

SCBCX13S2PC011654	SCBCG2ZG2PC011758	SCBCG13S7PC011861	SCBCG13S6PC011950	SCBCT2ZGXP012037
SCBCG13SXPC011658	SCBC113SXPC011760	SCBCW13S7PC011863	SCBDX33S1PC011953	SCBCG13S9PC012039
SCBDW33S4PC011660	SCBCG13S5PC011762	SCBDW33S2PC011866	SCBCW13S1PC011955	SCBCG13S9PC012042
SCBCG13S1PC011662	SCBCX13S9PC011764	SCBC113S8PC011868	SCBCJ13S7PC011957	SCBDT4ZG7PC012044
SCBDT4ZGXP011664	SCBDJ33S0PC011766	SCBCG13S1PC011869	SCBCG13S2PC011959	SCBDT4ZG4PC012048
SCBCG13S2PC011668	SCBCT2ZG8PC011775	SCBCG13SXPC011871	SCBDG4ZGXP011961	SCBCG13S8PC012050
SCBDT4ZG5PC011670	SCBDT4ZG1PC011777	SCBCG13S3PC011873	SCBCG13S4PC011963	SCBCG13S1PC012052
SCBCK13S6PC011672	SCBDT4ZG3PC011781	SCBCW13S3PC011875	SCBCG13S8PC011965	SCBCG13S5PC012054
SCBCJ13S6PC011674	SCBCX13S2PC011783	SCBDG4ZGXP011877	SCBDX33S1PC011967	SCBD133S7PC012056
SCBCJ13SXPC011676	SCBCG2ZG5PC011785	SCBCW13S0PC011879	SCBCT2ZGXP011969	SCBCG13S2PC012058
SCBCT2ZGXP011678	SCBCJ13S8PC011787	SCBCG13S2PC011881	SCBCW13SXPC011971	SCBCG13S0PC012060
SCBCT2ZG8PC011680	SCBCG13S3PC011792	SCBDG4ZG5PC011883	SCBDG4ZG6PC011973	SCBCJ13S2PC012062
SCBCK13S9PC011682	SCBCG2ZGXP011796	SCBCK13S1PC011885	SCBCG13S0PC011975	SCBCG13S8PC012064
SCBCG13S0PC011684	SCBDT4ZG9PC011798	SCBCG13S3PC011887	SCBCG13S8PC011979	SCBDT4ZG6PC012066
SCBC113S6PC011688	SCBCJ13S7PC011800	SCBDX33S7PC011889	SCBDW33S2PC011981	SCBCG13S5PC012068
SCBD133S4PC011690	SCBDG4ZG3PC011803	SCBCJ13S3PC011891	SCBCG13SXPC011983	SCBDT4ZG8PC012070
SCBCT2ZG4PC011692	SCBCH13S1PC011805	SCBDW33S5PC011893	SCBDJ33S5PC011987	SCBCT2ZG9PC012076
SCBCK13S9PC011701	SCBC113S8PC011806	SCBCG13S2PC011895	SCBCW13S7PC011989	SCBCG13S6PC012080
SCBCT2ZG5PC011703	SCBDX33S3PC011808	SCBC11ZG7PC011900	SCBCG13S9PC011991	SCBC113SXPC012083
SCBCT2ZG9PC011705	SCBCG13S1PC011810	SCBCG13S6PC011902	SCBDW33S9PC011993	SCBDH33S9PC012085
SCBC113S6PC011707	SCBDX33S5PC011812	SCBCW13S6PC011904	SCBCW13S2PC011995	SCBCT2ZG3PC012087
SCBCJ13S8PC011711	SCBCX13S9PC011814	SCBDG4ZG2PC011906	SCBCG13SXPC011997	SCBCG13S2PC012089
SCBCX13S7PC011715	SCBCG13S6PC011818	SCBCG13S7PC011908	SCBDV33S6PC011999	SCBC113S9PC012091
SCBDT4ZG5PC011717	SCBCG13S4PC011820	SCBDX33S5PC011910	SCBCG13S6PC012001	SCBCG13S8PC012095
SCBD133S0PC011721	SCBCK13SXPC011822	SCBCG13S9PC011912	SCBCW13S6PC012003	SCBCG13S5PC012099
SCBCW13S2PC011723	SCBCX13S9PC011828	SCBDW33S9PC011914	SCBCT2ZG1PC012007	SCBDT4ZG8PC012103
SCBDK33S1PC011725	SCBCG13S7PC011830	SCBCG13S6PC011916	SCBD133S9PC012009	SCBCG13S7PC012105
SCBCG13S7PC011729	SCBCG13S9PC011831	SCBDV33S0PC011920	SCBCW13S5PC012011	SCBD133S9PC012107
SCBCK13S0PC011733	SCBC113S0PC011833	SCBCX13SXPC011921	SCBDT4ZG7PC012013	SCBCT2ZG9PC012112
SCBCG2ZG1PC011735	SCBCK13S8PC011835	SCBC113S1PC011923	SCBCG13S6PC012015	SCBCG13S8PC012114
SCBCX13S8PC011738	SCBDT4ZG4PC011837	SCBCG13S7PC011925	SCBC113S8PC012017	SCBDT4ZG6PC012116
SCBCG13S6PC011740	SCBCG13S3PC011839	SCBCG13S0PC011927	SCBDT4ZG8PC012019	SCBCG13S5PC012118
SCBCW13S6PC011742	SCBC113SXPC011841	SCBCK13S6PC011929	SCBCT2ZG4PC012020	SCBCG13S3PC012120
SCBDT4ZG8PC011744	SCBCT2ZG7PC011847	SCBCX13S2PC011931	SCBCG13S3PC012022	SCBD133S5PC012122
SCBCG13S7PC011746	SCBCK13S8PC011849	SCBCG13SXPC011935	SCBDT4ZG5PC012026	SCBCT2ZG5PC012124
SCBDG4ZGXP011748	SCBCK13S6PC011851	SCBDX33S3PC011937	SCBCT2ZG9PC012028	SCBCG13S4PC012126
SCBCJ13S7PC011750	SCBDG4ZG7PC011853	SCBCG13S5PC011941	SCBCG13S2PC012030	SCBDT4ZG2PC012128
SCBCK13S4PC011752	SCBCW13S8PC011855	SCBDX33S9PC011943	SCBD133S4PC012032	SCBCG13S6PC012130
SCBDT4ZG0PC011754	SCBDW33S1PC011857	SCBCG13S2PC011945	SCBCT2ZG4PC012034	SCBCG13S3PC012134
SCBCG13SXPC011756	SCBCK13S0PC011859	SCBCW13S2PC011947	SCBDG4ZG0PC012035	SCBD133S9PC012138