

# **Preliminary Information**

# PIT6098 Wireless Charger Starts Charging And Stops Charging

**Proactive** 

## <u>Models</u>

Brand:	Model:		Model Years:	VIN:		Enginet	Transmissions:	
Di di lu.				from	to	Engine:	Transmissions.	
Cadillac	Lyriq		2023 - 2024	All	All	All	All	
Chevrolet	Colorado		2023 - 2024	All	All	All	All	
GMC	Canyon		2023 - 2024	All	All	All	All	
Involved Region o	or Country	North America						
Additional Options (RPO)		K4C						
Condition		1	Some customers may comment that the wireless charger starts charging and then stops charging.					
Cause		The cause is unknown at this time.						

### Correction:

Do not replace any parts at this time.

Engineering is aware of this concern and are investigating at this time.

Please communicate to the customer that we apologize for this inconvenience and that General Motors is working on a solution for this concern.

Once a solution is available, this PI will be updated with additional details.

### Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time		
*5486438	Verify wireless charger starts then stops charging	0.2 Hr.		
*This is a unique Labor Operation for Bulletin use only.				

**Version History** 

Version	1
Modified	12/11/2023 - Created On.



© 2024 General Motors. All Rights Reserved.