



Bulletin No.: PIP5869C
Published date: 01/24/2024

Preliminary Information

PIP5869C 5.5L RPO (LT6) Engine Exchange (GMNA Only) has ended Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Corvette	2023 - 2024	All	All	5.5L LT6	All

Involved Region or Country	North America
Condition	Engine Exchange Has Ended
Cause	New Product Monitoring

The Engine Exchange Program for the 5.5L LT6 engine has ended.

We would like to thank all dealers who participated in this exchange program for their cooperation.

The engine is now considered fully serviceable and dealers are recommended to use Service Information and TAC as needed for diagnostic and repair assistance.

This engine is currently on restriction and on 100% parts return, however can now be ordered through the regular GM CCA parts process.

Use the vehicle identification number (VIN) and the GM Electronic Parts Catalog to determine the correct part to order.

Version History

Version	4
Modified	09/13/2022 - Created on. 05/04/2023 - Update recommendations / instructions 12/04/2023 - Update model years and part numbers 01/24/2023 - Update recommendations / instructions and title

