## Audi of America, Inc.



Audi of America, Inc. 3800 Hamlin Road Auburn Hills, MI 48326 +1 248 754 5000 www.audiusa.com

Date: March 06, 2014

Subject: Action Closure Notification

Dear Audi Dealer Principal, Service Manager, and Parts Manager:

On March 06, 2014, the following actions will be closed:

13E9	UPDATE - Idler Roller (NVLW)
24V2	UPDATE - ECM Software Update (FED_EMS)
35B1	CUST_SAT - Mechatronic Unit
35B8	UPDATE - DSG Software Update (NVLW)
91H3	CUST_SAT - Rearview Camera Control Module
91H8	UPDATE - B&O Software (NVLW)
94E8	SERV_ACT - Xenon Headlights DRL

## Please note:

- Repairs under these actions must be completed by your close of business on March 6, 2014 in order to be eligible for payment consideration. Any repairs performed after that date will not be eligible for payment.
- Claims under these actions must be entered before your close of business on March 31, 2014. After this date, the system will not accept claims under these actions.
- No electronic funds transfer payments will be made to accommodate repairs or claims that miss the deadlines shown above.
- Dealers scheduling customer appointments under these actions are asked to keep the dates mentioned above in mind, and make every effort to complete repairs and claim entry in the timeframes shown.

**Code(s) Deactivation Date:** On March 6, 2014 the codes will be removed from ElsaWeb. The documents will remain on ServiceNet until March 31, 2014 so that the SAGA claiming instructions are available for reference when entering claims.

Thank you for your assistance in this important matter. If you have any questions or require additional assistance, please contact Warranty.

Audi Product Compliance