Subject: Engineering Information – Noise Heard from Transmission Area

This EI has been revised to end the need for gathering information from the field. Please discard PIE0767.

Brand:	Model:	Model Year:		VIN Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Corvette	2023	2024	_	_	_	Equipped with 8–SPD Automatic (RPO M1L)

If you encounter a vehicle with the above condition, refer to Service Bulletin # 21-NA-049 for further diagnosis.

Version	2
Modified	Released November 14, 2023 Revised February 14, 2024 – Ended the need for gathering further information from the field.